

TRADE TRAINING II-III TTC PROGRAMME



TURNER























GOVERNMENT OF THE PUNJAB
TECHNICAL EDUCATION & VOCATIONAL TRAINING AUTHORITY
TRADE TESTING BOARD
DEVELOPMENT CELL LAHORE

T.T.P. Series No.25

Price Rs.45.00



 Longitudinal turning 1	 Turning between Centres 2 → 4.2.2/2	 Drilling, Reaming 3 → 13	 Drilling, Grooving 4
 Longitudinal and Taper turning 5 → 4.2.1/9	 Internal turning 6	 Thread cutting 7	 Turning of Brass 8
 Thread cutting 9	 Stepturning 10	 Thread cutting 11	 Fitting 12
 Internal taper turning 3 → 13	 Knurling, Longitudinal turning 14 → 4.2.2/5	 Internal & External thread cutting 15	 Thread cutting, Work with steadyrest 16 → 3.3.1/2
 Bush fitting 17	 Left hand thread cutting 2.3.6/5 → 18 → 3.3.1/2	 Internal Acme thread cutting 3.2/3 → 19 → 3.3.1/2	 Test piece 20 → 4.3.2/1

In addition to the exercises shown above, the trainees have to make parts which are needed for the training centre.

TRADE
TRAINING II

LAYOUT

MP/2.1/3.11

TURNING II



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

FAK GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

MATERIAL REQUIRED

TURNER

TRADE TRAINING II

TURNING II
No. 3.1.1./1 to 20

	Exercise No (Length given in Millimeter)										Length per trainee	Total Length for 16 trainees	Total weight for 16 trainees		
	1	2	1	2	2	3	2	4	2	5				6	7
MILDSTEEL ϕ 38mm 1 1/2" DIA	156												156 mm	2.5 meter	22.25 kg
CARBON STEEL ϕ 22mm 7/8" DIA	156												156 //	FOR 4 Trainees	1.9 //
CARBON STEEL ϕ 26 mm 1 1/16" DIA	156	156	156	156									468 //	FOR 9 Trainees	18.9 //
CARBON STEEL ϕ 29mm 1 1/8" DIA				156									156 //	FOR 3 Trainees	2.6 //
MILDSTEEL ϕ 50mm 2" DIA				60									60 //	0.96 //	11.4 //
CASTIRON ϕ 88mm (Block)					45								45 //	0.72 //	CAST IRON AS PER PATTERN.
HIGH SP. STEEL ϕ 19mm 3/4" DIA						220							220 //	3.5 //	9.3 kg
MILDSTEEL SQUARE 44x44mm 13/4" x 1 3/4"							45						45 //	0.72 //	10 //
8 M.S. PIPE ϕ 16mm 5/8" DIA										101			101 //	1.6 //	Running meas. 1.7 meter
M.S. ROUND ϕ 30mm 1 1/4" DIA											50		50 //	0.8 //	4.4 kg
M.S. ROUND ϕ 44mm 1 3/4" DIA												16	16 //	0.26 //	2.8 //

Continued



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

MATERIAL REQUIRED

TURNER

TRADE TRAINING II

TURNING II

No.3.1.1/8to13

Exercise No. (Length given in millimeter)

	Exercise No. (Length given in millimeter)										Length per trainee	Total length for 16 trainees	Total weight for 16 trainees			
	8.1	8.2	8.3	9.1	9.2	10	11.1	11.2	11.3	12.1				12.2	13.1	13.2
BRASS ϕ 16mm 5/8" DIA	56													56 mm	0.9meter	1.42 kg
BRASS ϕ 25mm 1" DIA		21												21 mm	0.34meter	1.36 kg
BRASS ϕ 14mm 9/16" DIA			81											81 mm	1.3meter	1.57 kg
MILD STEEL ϕ 32 mm 1 1/4" DIA				56	56				35					147mm	2.35meter	14.83kg
M.S. ϕ 51mm 2" DIA						53	26					56	26	171mm	2.74meter	43.6 kg
M.S. ϕ 38mm 1 1/2" DIA								31						31 mm	0.5 meter	4.45 kg
M.S. ϕ 28mm 1 1/8" DIA										61	61			122mm	2meter	9.66 kg

Continued



MATERIAL REQUIRED

TRADE TRAINING II

TURNER

TURNING II

No.3.1.1/14to20


Exercise No. (Length given in Millimeter)

	141	142	143	151	152	153	16	171	172	181	182	19	201	202	203	Length per trainee	Total length for 16 trainees	Total weight for 16 trainees
M.S. ROUND ϕ 22mm 7/8" DIA	120															390 mm	6.24 meter	18.6 kg
M.S. ROUND ϕ 32mm 1 1/4" DIA	2	24	96													141 //	2.3 //	14.5 //
M.S. ROUND ϕ 50mm 2" DIA				25	25	56										106 //	1.7 //	27.2 //
M.S. ROUND ϕ 28mm 1 1/8" DIA						335										335 //	5.36 //	25.9 //
M.S. ROUND ϕ 75mm 3" DIA							57									57 //	0.91 //	32.2 //
M.S. ROUND ϕ 38 mm 1 1/2" DIA									121							121 //	1.94 //	17.3 //
M.S. FLAT 38x19mm 1 1/2" x 3/4"										82						82 //	1.3 //	73 //
M.S. FLAT 38x25mm												106				106 //	1.7 //	13 //
													30	8	38	30 8 38 //	0.61 //	4 //




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME





Exercise No	ϕA	ϕB	C	Marks given
1.1	$36 \pm 0,2$	$30 \pm 0,2$	$50 \pm 0,2$	
1.2	$32 \pm 0,1$	$26 \pm 0,1$	$52 \pm 0,1$	
1.3	$30 + 0,1$	$24 + 0,1$	$54 + 0,1$	
1.4	$26 - 0,1$	$21 - 0,1$	$56 - 0,1$	

SCALE 1:1	MEASURING EXERCISE	MP/23/ 3.1.1/1
MAT:MILDSTEEL		TURNING II
 DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING PAK-GERMAN TECHNICAL TRAINING PROGRAMME		TURNER

FOR ALL DIMENSIONS :0.1
UNLESS OTHERWISE STATED




8



Grinding ϕ	ϕ A	ϕ B	C
ϕ 20	20,5	17	15
ϕ 21	21,5	18	16
ϕ 22	22,5	19	17
ϕ 23	23,5	20	18
ϕ 24	24,5	20	18

SCALE 1:1	<h1>Mandrel</h1>	MP/2.3/3.1.1/2
MAT. CARBON ST.		TURNING II
 DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING PAK-GERMAN TECHNICAL TRAINING PROGRAMME		<h2>TURNER</h2>



CHECK THE FOLLOWING POINTS VERY CAREFULLY

1. 54 ± 0.1
2. $\varnothing 48 \pm 0.1$
3. $\varnothing 42 - 0.1$
4. $\varnothing 42 - 0.1$
5. $\varnothing 28 + 0.1$
6. $26 + 0.1$
7. $18 + 0.1$
8. $10 + 0.1$
9. Smoothness of bore
10. Smoothness all over

The shoulder in the bore must be in right angle !

SCALE 1:1

BUSH

MP/23/ 31.1/ 3

MAT: MILDSTEEL

TURNING II




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

TOLERANCE $\pm 0,1$



CHECK THE FOLLOWING POINTS VERY CAREFULLY

1. $\phi 68 - 0,1$
2. $\phi 42 - 0,1$
3. $\phi 40 + 0,1$
4. $\phi 32 + 0,1$
5. $40 \pm 0,1$
6. $16 - 0,1$
7. $8 + 0,1$
8. $16 - 0,1$
9. $10 + 0,1$
10. Smoothness all over

Mind the hard casting skin when you choose the depth of the first cut !

SCALE 1:1

MAT CAST IRON

PULLEY

MP/2.3/3.1.1/4


TURNING II



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER



(Wavy line symbol) GRINDING

TOLERANCE ± 0.1

CHECK THE FOLLOWING POINTS VERY CAREFULLY

1. ϕ 16.4
2. ϕ 18.2
3. 125
4. 80
5. 14

Use the Taper gauge to check the taper Morse No. 2

SCALE 1:1

DRILL BODY

MP/23/ 311/5

MAT HIGH SP. ST.


TURNING II



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER



CHECK THE FOLLOWING POINTS VERY CAREFULLY

1. $\varnothing 35 + 0.1$
2. $\varnothing 25 + 0.1$
3. $\varnothing 15 + 0.1$
4. $13.5 + 0.1$
5. $9.0 + 0.1$
6. $4.5 + 0.1$
7. Smoothness of stepped hole 35 mm
8. Smoothness of stepped hole 25 mm
9. Smoothness of stepped hole 15 mm
10. Smoothness all over

Use a suitable filling disc when chucking the ready machine side !

SCALE 1:1

PAPER WEIGHT

MP/23/ 311/6

MAT: MILDSTEEL

TURNING II




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

TOLERANCE $\pm 1/54''$



CHECK THE FOLLOWING POINTS VERY CAREFULLY

1. Smoothness pipe thread R 1/2 " x 1 3/4 " - Piece No. 1
2. Smoothness pipe thread R 1/2 " x 5/8 " - Piece No. 1
3. Smoothness drilled hole \varnothing 5/8 " - Piece No. 1
4. Smoothness pipe thread R 1/2 " x 1 3/4 " - Piece No. 2
5. Smoothness outside diameter 1 1/16" x 1 3/4 " - Piece No. 2
6. Accuracy of pipe thread connection R 1/2 " - Piece No. 1 + 2
7. Smoothness pipe thread R 1/2 " x 3/8 " - Piece No. 3
8. Smoothness of faces - Piece No. 3
9. Accuracy of pipe thread connection R 1/2 " - Piece No. 1 + 3
10. Smoothness and accuracy all over - Piece No. 1 + 3

Prepare parts 2 and 3 first and check part 1 with their help !

SCALE 1:1

MAT. MILDSTEEL

PIPE LONG - THREADING

MP/2-3/ 3.11/7


TURNING II



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

FAY GERMAN TECHNICAL TRAINING PROGRAMME


TURNER




CHECK THE FOLLOWING POINTS VERY CAREFULLY

1. 50 \pm 0.1 - Piece No. 1
2. ϕ 14.7 - 0.1 - Piece No. 1
3. ϕ 12.2 - 0.1 - Piece No. 1
4. 16 - 0.1 - Piece No. 2
5. ϕ 22 - 0.1 - Piece No. 2
6. ϕ 12.8 + 0.1 - Piece No. 2
7. 38 - 0.1 - Piece No. 3
8. 38 - 0.1 - Piece No. 3
9. ϕ 12 - 0.1 - Piece No. 3
10. Smoothness all over- Piece No. 1 - 3

Mind that the cutting angles for brass differ from those for steel !

SCALE 1:1	RUBBER PIPE CONNECTION	MP/2.3/3.1.1/8
MAT-BRASS		TURNING II
 DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING PAR-GERMAN TECHNICAL TRAINING PROGRAMME		TURNER

TOLERANCE $\pm 1/64$



CHECK THE FOLLOWING POINTS VERY CAREFULLY

- | | | |
|----------------------------------|---------------|-------------------|
| 1. Smoothness pipe thread | R 1/2" x 7/8" | - Piece No. 1 |
| 2. Smoothness pipe thread | R 1/2" x 5/8" | - Piece No. 1 |
| 3. Smoothness drilled hole | ϕ 1/4" | - Piece No. 1 |
| 4. Smoothness of faces | | - Piece No. 1 |
| 5. Smoothness pipe thread | R 1/2" x 7/8" | - Piece No. 2 |
| 6. Smoothness pipe thread | R 1/2" x 3/4" | - Piece No. 2 |
| 7. Smoothness outside diameter | 1 1/8" | - Piece No. 2 |
| 8. Smoothness of face and radius | | - Piece No. 2 |
| 9. Accuracy of connection | R 1/2" right | - Piece No. 1 + 2 |
| 10. Accuracy of connection | R 1/2" left | - Piece No. 1 + 2 |

Mind the left hand and right hand threads on both workpieces !

SCALE 1:1

MAT. MILDSTEEL

DOUBLE NIPPLE AND SOCKET

MP/23/ 3.1.1/9


TURNING II




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK GERMAN TECHNICAL TRAINING PROGRAMME

TURNER



Tolerance $\pm 0,1$
unless otherwise stated



SEQUENCE OF OPERATION

1. Clamp the workpiece in the chuck, drill and bore (ream) the holes 18H7 and $\phi 30 + 0.02$. Prepare the internal recess $\phi 36$.
2. Turn the diameter $48 - 0.05$ roughly (48.5).
3. Clamp on rough turned diameter 48.5 and check for true running, then bore $\phi 26 + 0.2$.
4. Hold the workpiece on a mandrel and finish the outside diameters and grooves according to the drawing.

Check the recess in the bore with spring caliper.

SCALE 1:1

MAT. MILD STEEL

STEPPED BUSH

MP/2.3/3.1.1/10

TURNING II




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

TOLERANCE : 0.1



Material : Mild - steel


CHECK THE FOLLOWING POINTS VERY CAREFULLY

1. Smoothness pipe thread R 1 " x 12
2. Smoothness pipe thread R 1 " x 10
3. Smoothness pipe thread R 1/2 " x 16
4. Smoothness pipe thread R 1/2 " x 15
5. Accuracy of pipe thread connection R 1"
6. Accuracy of taper fit
7. Accuracy and smoothness all over
8. Accuracy and smoothness all over
9. Accuracy and smoothness all over
10. Accuracy and smoothness all over

- Piece No. 1
- Piece No. 2
- Piece No. 2
- Piece No. 3
- Piece No. 1 + 2
- Piece No. 2 + 3
- Piece No. 1
- Piece No. 2
- Piece No. 3
- Piece No. 1 - 3

Complete part 1 first and cut the 1" thread on part 2 to fit with it !

SCALE 1:1	UNION NUT	MP/23/ 3.1.1/11
MAT: MILDSTEEL		TURNING II
DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING		TURNER
PAK-GERMAN TECHNICAL TRAINING PROGRAMME		



CHECK THE FOLLOWING POINTS VERY CAREFULLY

- | | | |
|-----|------------------------------------|-------------------|
| 1. | 55 - 0.1 | - Piece No. 1 |
| 2. | 51 + 0.1 | - Piece No. 1 |
| 3. | ∅ 25 - 0.1 | - Piece No. 1 |
| 4. | ∅ 15 ± 0.03 | - Piece No. 1 |
| 5. | 55 - 0.1 | - Piece No. 2 |
| 6. | ∅ 25 - 0.1 | - Piece No. 2 |
| 7. | ∅ 15 ± 0.03 | - Piece No. 2 |
| 8. | Accuracy and smoothness of notches | - Piece No. 2 |
| 9. | Accuracy of bolt connection | - Piece No. 1 + 2 |
| 10. | Smoothness all over | - Piece No. 1 + 2 |

Check the compression of the unit by closing the ∅ 5 mm hole with the finger-tip !

SCALE:1:1

PLUNGER AND ZYLINDER

MP/23/ 3.1.1/12

MAT:MILDSTEEL

TURNING II






DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

TOLERANCE ± 0.2



CHECK THE FOLLOWING POINTS VERY CAREFULLY

- | | | |
|-----|---|-----------------|
| 1. | 50 ± 0.1 | - Piece No. 1 |
| 2. | $\phi 47 \pm 0.1$ | - Piece No. 1 |
| 3. | $\phi 40 \pm 0.1$ | - Piece No. 1 |
| 4. | $\phi 24 + 0.05$ | - Piece No. 1 |
| 5. | Accuracy of fine pitch thread M 38 x 1.5- | Piece No. 1 |
| 6. | Accuracy of taper 1 : 5 | - Piece No. 1 |
| 7. | Smoothness all over | - Piece No. 1 |
| 8. | Accuracy of fine pitch thread M 38 x 1.5- | Piece No. 2 |
| 9. | Accuracy and smoothness all over | - Piece No. 2 |
| 10. | Accuracy of thread connection M 38 x 1.5- | Piece No. 1 + 2 |

Check the taper with a taper gauge !

SCALE 1:1

MAT: MILDSTEEL

TAPERBUSH WITH RINGNUT

FROM EX.3

MP/2.3/3.1.1/13

TURNING II




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

TOLERANCE : 0.1



CHECK THE FOLLOWING POINTS VERY CAREFULLY

1. ϕ 12 - 0.02 - Piece No. 1
2. ϕ 30.2 - 0.03 - Piece No. 2
3. ϕ 30.2 - 0.03 - Piece No. 3
4. ϕ 8 - 0.02 - Piece No. 3
5. Fit - Piece No. 1 + 2
6. Fit - Piece No. 1 + 3
7. Smoothness ϕ 30.2 - Piece No. 2
8. Smoothness ϕ 30.2 - Piece No. 3
9. Knurling 1 mm - Piece No. 1
10. Smoothness all over - Piece No. 1 - 3

Check bores ϕ 8 and ϕ 12 with plug gauges !

SCALE 1:1

MAT: MILDSTEEL

PLUG GAUGE

MP/2.3/3.11/14


TURNING II



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER



Material: Mild-steel

CHECK THE FOLLOWING POINTS VERY CAREFULLY

1. 90 ± 0.1
 2. $30 - 0.1$
 3. $30 - 0.1$
 4. $20 - 0.1$
 5. $20 - 0.1$
 6. Accuracy of fine pitch thread M 27 x 1.5
 7. Thread fit M 27 x 1.5
 8. Accuracy of metric-thread M 27
 9. Thread fit M 27
 10. Smoothness all over
- Piece No. 1
- Piece No. 1
- Piece No. 1
- Piece No. 2
- Piece No. 3
- Piece No. 1 + 2
- Piece No. 1 + 2
- Piece No. 1 + 3
- Piece No. 1 + 3
- Piece No. 1 - 3

Find out the pitch of M 27 from the table book !

SCALE
MAT. MILD STEEL

SCREW FITTING

MP/23/3.1.1/15
TURNING II





DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

$\varnothing 30_{H6}$ • 0.033
• 0.017



CHECK THE FOLLOWING POINTS VERY CAREFULLY

1. ϕ 16
2. ϕ 14 - 0.2

Before starting thread cutting check the pitch.

The raw piece is to be cut to a length of about 335 mm so that a centre bore can be made as shown in the detail to allow the use of a tailstock centre. After completing all operations (thread cutting) the spindle is to be clamped with the thread in a collet chuck or with the head in the three jaw chuck and the ϕ 12 in the steady rest to allow completion of the 120° end.

SCALE 1:1

MAT: MILDSTEEL

SPINDLE

MP/23/ 3.1.1/16

TURNING II





DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING


PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER



TOLERANCE FOR ALL DIM. 10.1
UNLESS OTHERWISE STATED



SCALE 1:1	BUSH FITTING	MPI/2.3/ 3.11/17
MAT MILDSTEEL		TURNING II
 DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING PAK-GERMAN TECHNICAL TRAINING PROGRAMME		TURNER



MATERIAL: MILD-STEEL



SCALE 1:1

MAT: MILDSTEEL

SCREW SOCKET AND NUT

FROM 23.6/5

MP/23/3.1.1/18


TURNING 11



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER



SEQUENCE OF OPERATION

1. Mount four jaws chuck on Lathe Machine.
2. Hold finished milled workpiece in four jaws chuck and check true running.
3. Bore core diameter for Acme thread 27 x 3.
4. Cut left hand Acme thread.

CAUTION

Check the thread with the male piece.

SCALE 1:1

MAT: MILDSTEEL

LINK PIECE

FROM 3.2/3

MP/23/ 3.1.1/19

TURNING II







DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

Tolerance ± 0.1



Material: Mild-steel
Brass

SCALE 1:1

SPINDLE AND THREAD BUSH

MP/23/ 3.1.1/ 20

MAT:














TURNING II



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

		
<p>Parallel and right angle shaping</p>  <p>1 — 2 → 5</p>	<p>Shaping of Cast iron</p> <p>3 → 4.1.1/6</p>	<p>Step shaping</p> <p>4 → 4.1.1/8</p>
 <p>Shaping of grooves</p> <p>1 → 5 → 6</p>	 <p>Angular shaping</p> <p>5 → 6 → 3.2.4/8</p>	 <p>Rack shaping</p> <p>7</p>
 <p>Dove tail shaping, external</p> <p>8</p>	 <p>Dove tail shaping internal</p> <p>9</p>	 <p>Form shaping</p> <p>10 → 4.1.2/5</p>
 <p>Step shaping</p> <p>11</p>	 <p>Internal form shaping</p> <p>12</p>	 <p>External form shaping</p> <p>13</p>

In addition to the exercises shown above, the trainees have to make parts which are needed for the training centre.

TRADE
TRAINING II

LAYOUT

MP/2.1/ 3.1.2

SHAPING II



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

MATERIAL REQUIRED

TURNER

TRADE TRAINING II

SHAPING II
No.3.1.2/1 to 13


Exercise No. (Length given in Millimeter)

	Exercise No. (Length given in Millimeter)													Total Length for 16 trainees	Total weight for 16 trainees		
	1	2	3	4	5	6	7	8	9	10	11	12	13				
M.S. SQUARE 44x44mm 1 3/4" x 1 3/4" sq.	76	46									116				238 mm	3.8 meter	58.5 kg
CAST IRON 96x30mm 3 3/4" x 1 1/4"			106												106 "	17 "	37.0 "
CAST IRON 76x42 mm 3" x 1 3/4"				120											120 "	2 "	48.0 "
CAST IRON SQ. 44x44mm 1 3/4" x 1 3/4" sq.					156										156 "	2.5 "	36.0 "
M.S. SQ. 62x62 mm 2 1/2" x 2 1/2" sq.						26	26								52 "	0.84 "	25.5 "
CAST IRON 81x76mm 3 1/4" x 3"									156						156 "	2.5 "	114.0 "
M.S. SQUARE 75x75mm 3" x 3" sq.											25	25			50 "	0.8 "	35.5 "



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME



CHECK THE FOLLOWING POINTS VERY CAREFULLY

1. 40 ± 0.1
2. 40 ± 0.1
3. 70 ± 0.1
4. Angle A - B
5. Angle C - D
6. Angle A B C D - E
7. Angle A B C D - F
8. Parallel surface
9. Plane surface
10. Smoothness all over

Use parallel distance pieces to chuck the job
in the vice !

SCALE 1:1

MAT: MILD STEEL

V - BLOCK

MP/23/312/1


SHAPING!!



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME


TURNER




CHECK THE FOLLOWING POINTS VERY CAREFULLY

- 1. 40.2 + 0.1
- 2. 40.2 + 0.1
- 3. 40.2 + 0.1
- 4. Angle A - B
- 5. Angle C - D
- 6. Angle A B C D - E
- 7. Angle A B C D - F
- 8. Parallel surface
- 9. Plane surface
- 10. Smoothness all over

First shape two opposite surfaces parallel with each other !


SCALE 1:1	CUBE	MP/23/312/2
MAT: Mildsteel		SHAPING II
	DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING	TURNER
PAK-GERMAN TECHNICAL TRAINING PROGRAMME		




CHECK THE FOLLOWING POINTS VERY CAREFULLY

- 1. Angles
- 2. Parallel surfaces
- 3. Plane surfaces
- 4. Smoothness all over

Mind the hard casting skin when you choose the depth of the first cut !

SCALE 1:1	ECCENTRIC BORING PLATE	MP/23/ 3.1.2/3
MAT: CAST IRON		SHAPING II
 DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING PAK-GERMAN TECHNICAL TRAINING PROGRAMME		TURNER



CHECK THE FOLLOWING POINTS VERY CAREFULLY

1. $70 - 0.1$
2. $66 - 0.1$
3. $36 + 0.1$
4. $30 - 0.1$
5. $30 - 0.1$
6. $30 - 0.1$
7. $30 - 0.1$
8. Angle surface
9. Parallel surface
10. Smoothness all over

Machining of cast iron does not require any cooling liquid !

SCALE 1:1

MAT: CAST IRON

MOVEABLE NUT

MP/23/3.1.2/4

SHAPING II




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER


Tolerance ± 0.1
unless otherwise stated





CHECK THE FOLLOWING POINTS VERY CAREFULLY

1. 18 - 0.1
2. 17 - 0.1
3. 16 - 0.1
4. 19 + 0.1
5. 12 + 0.1
6. 8 \pm 0.1
7. 8 \pm 0.1
8. Notches, parallel and rectangular
9. Notches, smoothness
10. Smoothness all over

Grind the slotting tool to 4 mm width to shape the 4 mm slot !

SCALE 1:1	V-BLOCK	MP/23/ 3.1.2/5
MAT: MILDSTEEL Mat. from Ex 1		SHAPING II
 DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING PAK-GERMAN TECHNICAL TRAINING PROGRAMME		TURNER

Tolerance ± 0.2
unless otherwise stated



CHECK THE FOLLOWING POINTS CAREFULLY

1. $32 + 0.2$
2. 90°
3. $20 + 0.2$
4. Angle 90°
5. Parallel Surfaces
6. Smoothness all over

When checking the 90° angle the edge of the try-square must not touch the bottom of the groove !

SCALE 1:1

MAT: MILDSTEEL

from Ex 5

V-BLOCK

MP/23/3.1.2/6

SHAPING !!




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

Tolerance $\pm 0,1$



CHECK THE FOLLOWING POINTS VERY CAREFULLY

Modul : 3

1. 150 - 0.1
2. 38 - 0.1
3. 38 - 0.1
4. 6.5 - 0.1
5. 6.5 - 0.1
6. Accuracy of angle 60°
7. Dimensional accuracy of teeth 90°
8. Dimensional accuracy of teeth 60°
9. Angle and parallel surface
10. Smoothness all over

All teeth must be precisely parallel !

SCALE 1:1

MAT: CAST IRON

RACK

MP/2.3/3.1.2/7


SHAPING II



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

Tolerance $\pm 30'$ 

CHECK THE FOLLOWING POINTS VERY CAREFULLY

1. $60 - 0.1$
2. $60 - 0.1$
3. $50.3 - 0.1$
4. $20 - 0.1$
5. 10 ± 0.1
6. 10 ± 0.1
7. Angle 60°
8. Angle 60°
9. Angle and parallel surface
10. Smoothness all over

Debur carefully after shaping !

SCALE 1:1

DOVE TAIL

MP/23/3.1.2/8

MAT: MILDSTEEL

SHAPING II





DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

Tolerance $\pm 30'$



CHECK THE FOLLOWING POINTS VERY CAREFULLY

1. $60 - 0.1$
2. $60 - 0.1$
3. $16.1 + 0.1$
4. $40 + 0.1$
5. $20 - 0.1$
6. 10 ± 0.1
7. Angle 60°
8. Angle 60°
9. Angle and parallel surface
10. Smoothness all over


Check the dove tail with the matching piece shown in drawing no. 8 !

SCALE 1:1	DOVE TAIL	MP/2.3/3.1.2/9
MAT: MILDSTEEL		SHAPING II
 DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING PAK-GERMAN TECHNICAL TRAINING PROGRAMME		TURNER

36



Tolerance ± 0.1
unless otherwise stated



SEQUENCE OF OPERATION

1. Shape the base surface and recess 70 x 4.
2. Use this face as a reference to shape the width 70.
3. Shape to length 150.
4. Shape radius 35 mm and thickness 19 mm.
5. Chamfer 3 x 45°.

SCALE 1:1

MAT. CAST-IRON

BRACKET

MP/2-3/3.1.2/10


SHAPING II



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

Tolerance ± 0.1 

SCALE 1:1

MAT.MILD STEEL

CLAMPING TOOL

MP/2-3/3.1.2/11






SHAPING11



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER



SCALE 1:1
MAT: MILDSTEEL

TONGUE FITTING
















MP/ 23/ 3.1.2/12-13
SHAPING II



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

 <p>Longitudinal turning</p> <p>1 → 4.2.2/1</p>	 <p>Turning between centres</p> <p>2 → 4.2.2/1</p>	 <p>Double start thread cutting</p> <p>3</p>
 <p>Thread cutting</p> <p>4 → 4.3.2/2</p>	 <p>Knurling, Boring</p> <p>5 → 4.3.2/2</p>	 <p>Eccentric boring</p> <p>3.1.2/3 → 6</p>
 <p>Eccentric turning</p> <p>7</p>	 <p>Working on a four jaw chuck</p> <p>3.1.2/4 → 8</p>	 <p>Working on a Mandrel</p> <p>9</p>
 <p>Eccentric turning</p> <p>10 → 4.2.2/8</p>	 <p>Exercising of known operations</p> <p>11</p>	 <p>Exercising of known operations</p> <p>12</p>
 <p>Form turning</p> <p>13</p>	 <p>Assembling</p> <p>14</p>	 <p>Exercising of known operations</p> <p>15</p>

In addition to the exercises shown above, the trainees have to make parts which are needed for the training centre.

TRADE
TRAINING III

LAYOUT

MP/2.1/4.1.1

TURNING III



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

MATERIAL REQUIRED
TURNER

TRADE TRAINING III
TURNING III

No. 4.1.1/1 to 15	Exercise No.										Length per Trainee	Total length for 16 Trainees	Total weight for 16 Trainees			
	1.1	1.2	1.3	1.4	2.1	2.2	2.3	2.4	2.5	3.1				3.2	4.1	4.4
M.S.Round ϕ 44 mm (1 3/4" DIA)	156													156 mm	2.5 meter	30.6 kg
M.S.Round ϕ 38 mm (1 1/2" DIA)	156	156												312 mm	5 meter	44.5 kg
M.S.Round ϕ 32 mm (1 1/4" DIA)			156								307			468 mm	7.5meter	47.3 kg
Carbon St. ϕ 19 mm (3/4" DIA)					136	136	136							408 mm	6.53meter	14.56 kg
Carbon St. ϕ 22 mm (7/8" DIA)							136	136						272 mm	4.35meter	13 kg
M.S.Round ϕ 26 mm (1" DIA)									190					190 mm	3 meter	12.5 kg
M.S.Round ϕ 51 mm (2" DIA)										38				38 mm	0.29meter	9.6 kg
M.S.Round ϕ 19 mm (3/4" DIA)											28			28 mm	0.45meter	1 kg

continued



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TRADE TRAINING III

TURNING III

No. 4.1.1/

MATERIAL REQUIRED

TURNER

(Length given in Millimeter)

Exercise No.


Length per Trainee

No.	Exercise No.	(Length given in Millimeter)										Length per Trainee	Total length for 16 Trainees	Total weight for 16 Trainees					
		5.2	5.3	7	9	10	11	12	13	14	14.2				14.3	14.4	15.1	15.2	15.3
M.S.Round \varnothing 70mm (2 3/4" DIA)	56															56 mm	0.9 meter	27.0 kg	
M.S.Round \varnothing 63mm (2 1/2" DIA)	54															54 mm	0.86meter	21.3 kg	
Cast Iron \varnothing 86mm (3 3/8" DIA)	44															44 mm	0.7 meter	30.0 kg "CASTING"	
Cast Iron \varnothing 105mm (4 1/4" DIA)	46															46 mm	0.74meter	26.3 kg "CASTING"	
M.S.Round \varnothing 51mm (2" DIA)						142	91									233 mm	3.7 meter	60.0 kg	
M.S.Round \varnothing 82mm (3 1/4" DIA)										56						56 mm	0.9 meter	23.5 kg	
M.S.Round \varnothing 32mm (1 1/4" DIA)												131				131 mm	2.1 meter	13.3 kg	
M.S.Round \varnothing 22mm (7/8" DIA)													81			81 mm	1.3 meter	3.9 kg	
M.S.Squ. 25x25mm (1" squ.)														40		40 mm	0.64meter	3.3 kg	
M.S.Round \varnothing 82mm (3 1/4" DIA)														36		36 mm	0.58meter	23.2 kg	
M.S.Round \varnothing 63mm (2 1/2" DIA)														22		22 mm	0.35meter	8.75 kg	
M.S.Round \varnothing 25mm (1" DIA)															84	84 mm	1.34 meter	5.4 kg	
M.S.Round \varnothing 32mm (1 1/4" DIA)															21	24	45 mm	0.72meter	4.55 kg
M.S.Round \varnothing 50mm (2" DIA)																75	75 mm	1.2 meter	19.0 kg
M.S.Round \varnothing 44mm (1 3/4" DIA)																35	35 mm	0.56meter	6.74 kg



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME



Exercise No	ϕA	ϕB	C	Marks given
1.1	$38 \pm 0,03$	$34 \pm 0,03$	$40 \pm 0,1$	
1.2	$36 \pm 0,02$	$32 \pm 0,02$	$42 \pm 0,1$	
1.3	$33 \pm 0,02$	$29 \pm 0,02$	$44 \pm 0,1$	
1.4	$30 \pm 0,01$	$27 \pm 0,01$	$46 \pm 0,1$	

Diameters must be checked with the Micrometer 25 to 50 mm.

SCALE 1:1

MAT: MILDSTEEL

MEASURING EXERCISE

MP/23/4.11/1'

TURNING III





DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

TOLERANCE ± 0.1



Grinding \varnothing	$\varnothing A$	$\varnothing B$	C
$\varnothing 15$	15,2	13	12
$\varnothing 16$	16,2	14	12,5
$\varnothing 17$	17,2	14,5	13
$\varnothing 18$	18,2	15	13
$\varnothing 19$	19,2	16	14

SCALE 1:1

MAT. CARBON ST.

Mandrel

MP/2.3/4.1/2

TURNING III



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME


TURNER



47

Tolerance ± 0.1
unless otherwise stated

47



CUTTING A MULTIPLE THREAD, PROCEED AS IF CUTTING A SINGLE THREAD OF THE REQUIRED LEAD BY USING A TOOL ACCORDING TO THE GIVEN PITCH.

AFTER CUTTING THE FIRST THREAD GROOVE, IT IS NECESSARY TO GIVE THE WORK EXACTLY HALF A TURN WITHOUT TURNING THE LEAD SCREW.

USE THE METHOD TO DISENGAGE THE INTERMEDIATE GEAR FROM THE SCREW GEAR TO MOVE THE LATHE SPINDLE ONE HALF TURN.

SCALE 1:1

MAT. MILD STEEL

SPINDLE AND NUT (with double thread)

MP/2.3/4.1/3

TURNING III




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING



PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

FOR ALL DIMENSION ± 0.1
UNLESS OTHERWISE STATED




Acme threads $\phi 26 \times 5$ mm pitch



1	Washer		St 37	5	$\phi 30 \times 3$
1	Hexagon bolt	DIN 558	St 37	4	M8 X 10
1	Spindle		St 37	1	$\phi 30 \times 302$
REQD	NAME	STANDARD	MATERIAL	NO	SIZE

SCALE 1:1	DETAIL OF SUPPORT	MP/2.3/4.1.1/4
MAT. MILD STEEL		TURNING III

	DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING	TURNER
	PAK-GERMAN TECHNICAL TRAINING PROGRAMME	




Hold the nut by using the ready spindle as a mandrel to turn ϕ 42 and groove.

1	Head		St 37	3	ϕ 60 X 50
1	Nut		St 37	2	ϕ 70 X 52
REQD	NAME	STANDARD	MATERIAL	NO	SIZE


SCALE 1:1	DETAIL OF SUPPORT	MP/2.3/4.1.1/5
MAT. MILDSTEEL		TURNING III

	DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING	TURNER
	PAK-GERMAN TECHNICAL TRAINING PROGRAMME	




Sequence of Operation

1. Mark and center the workpiece
2. Clamp the workpiece on the face plate
3. Rough the bores
4. When finishing, check the diameter with the internal dial test indicator

SCALE 1:1	ECCENTRIC BORING PLATE	MP/2.3/4.1/1/6
MAT. CAST IRON	<small>From 312/6</small>	TURNING III
 DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING		TURNER
PAK-GERMAN TECHNICAL TRAINING PROGRAMME		

FOR ALL DIMENSIONS ± 0.1
UNLESS OTHERWISE STATED



SEQUENCE OF OPERATION

1. Hold workpiece in 3-jaw chuck, face and turn outside $\phi 80 \times 21$.
2. Turn step $\phi 70 \times 5$. Re-chuck, face to length 35 mm.
3. Turn step $\phi 70 \times 15$.
4. Mark out excentre 15 mm and centre drill with the help of drilling machine.
5. Mount 4-jaw chuck.
6. Hold workpiece in such a way that the previously drilled centre hole runs true.
7. Turn excentre $\phi 40 \times 10$ and radius 2.
8. Pre-drill and drill $\phi 24.5$
9. Mount boring tool and finish hole to $\phi 25$.

SCALE 1:1

MAT: CAST IRON

ECCENTRIC SHEAVE

MPI/23/4.1.17



TURNING III



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

Tolerance ± 0.1 SEQUENCE OF OPERATION

1. Mark out the centres and drill.
2. Hold in 4-jaw chuck, pre-drill and bore hole $\phi 33$.
3. Hold between centres and turn both sides to $\phi 25_{e8} \times 20$.

25 e8	-0.040
	-0.078

SCALE 1:1

MAT: CAST IRON

From 312/4

MOVEABLE NUT

MP/2.3/4.1/8

TURNING III




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

▽ (▽▽)

FOR ALL DIMENSIONS ± 0.1
UNLESS OTHERWISE STATED



Turn the outside diameter by using a mandrel to ensure true running.

25	H7	+0.021 0.000
----	----	-----------------

SCALE 1:1

MAT CAST IRON

PULLEY

MP/2.3/4.1.1/9

TURNING III





DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

FOR ALL DIMENSION ±0.1
UNLESS OTHERWISE STATED



SEQUENCE OF OPERATION

1. Face to the length of 135 mm
2. Mark and drill all 6 centres.
3. All other operations are to be completed with the workpiece held between centres.

28 ϕ h8	0.000 -0.033
15 ϕ h8	0.000 -0.027

SCALE 1:1
MAT: MILDSTEEL

CRANK SHAFT

MP/2.3/4.1/10
TURNING III





DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME


TURNER

FOR ALL DIMENSIONS : 0.1
UNLESS OTHERWISE STATED




SEQUENCE OF OPERATION

1. Turn $\phi 26$ to oversize 27 in the first step.
2. Hold $\phi 27$ in the three jaw chuck and complete knurled and threaded portions of the job.
3. Keep this job till the nut M 24 x 2 is ready as it will be needed for holding the screw during the finishing operations.

SCALE 1:1	MOVEABLE SCREW	MP/2.3/4.1.1/11
MAT: MILDSTEEL		TURNING III
 DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING		TURNER
PAK-GERMAN TECHNICAL TRAINING PROGRAMME		

FOR ALL DIMENSIONS $\pm 0,1$
UNLESS OTHERWISE STATED



SEQUENCE OF OPERATION

1. Face one end roughly and turn to $\phi 81$ at a length of about 15 mm.
2. Clamp $\phi 81$ in the three jaw chuck and complete all turning, boring and threading operations as far as possible in this position.
3. Now use the workpiece to hold the screw from the previous exercise for the necessary operations.
4. Clamp $\phi 45$ and complete the base.

SCALE 1:1

MAT: MILDSTEEL

BASE FOR MOVEABLE SCREW

MP/23/4.1.1/12


TURNING III



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER



SCALE 1:1

MAT. MILDSTEEL

BASE AND MOVEABLE SCREW

MP/23/4.11/12 a




TURNING III



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER



SCALE 1:1

MAT. MILDSTEEL

MACHINE HANDLE

MP/23/4.11/13






TURNING III




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME




TURNER



SCALE 1:1	SPINDLE AND CENTRE	MP/23/4.11/14
MAT: MILDSTEEL		TURNING III
 DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING PAK-GERMAN TECHNICAL TRAINING PROGRAMME		TURNER















FOR ALL DIMENSIONS $\pm 0,1$
UNLESS OTHERWISE STATED



After facing the job and marking the 4 centres a hole of about 12 mm depth and about 3 mm diameter is to be drilled in place X. This will provide a guide hole for the centre drill later.

SCALE 1:1	ECCENTRIC TAPER BOLT	MP / 23/411/15
MAT. MILDSTEEL		TURNING III
 DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING PAK-GERMAN TECHNICAL TRAINING PROGRAMME		TURNER

 <p>Exercising of known operations</p> <p>1 → 3</p>	 <p>Turning within small tolerances</p> <p>2 → 5</p>	 <p>Turning of welded parts</p> <p>1 → 3 → 5</p>
 <p>Turning of internal grooves</p> <p>4 → 5</p>	 <p>Working on a four jaw chuck</p> <p>3.1.2/10 → 5 ← 2/3/4</p>	 <p>Work with steadyrest</p> <p>6</p>
 <p>Facing of grooves</p> <p>7</p>	 <p>Boring to high accuracy</p> <p>8 → 4.21/9</p>	 <p>Taper turning</p> <p>9</p>
 <p>Exercising of known operations</p> <p>10</p>	 <p>Exercising of known operations</p> <p>11 → 4.2.1/11</p>	 <p>Eccentric shaft</p> <p>12</p>

In addition to the exercises shown above, the trainees have to make parts which are needed for the training centre.

TRADE
TRAINING III

LAYOUT

MP/2.1/4.1.2

TURNING IV



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

TRADE TRAINING III
TURNING IV



MATERIAL REQUIRED
TURNER

No.	4.1.2/1 to 12	Exercise No.	(Length given in Millimeter)											Length per Trainee	Total length for 16 Trainees	Total weight for 16 Trainees								
		1,1	1,2	2	4	6	7	8	9	10	11	12	13	14	15	16	17	18						
M.S.Round ϕ 50 mm (2" DIA)		48				106										16	150	46				366 mm	5.9 meter	93.8 kg
M.S.Round ϕ 130 mm (5 1/4" DIA)		30																				30 mm	0.48 meter	52.3 kg
M.S.Round ϕ 38 mm (1 1/2" DIA)									106	68												351 mm	5.62 meter	47.6 kg
M.S.Round ϕ 75 mm (3" DIA)											16											16 mm	0.256 meter	9.0 kg
Cant Iron acc. to pattern																						casting		
Cast Iron ϕ 105 mm (4 1/4" DIA)											28											28 mm	0.45 meter	30.5 kg "CASTING"
M.S.Round ϕ 102 mm (4" DIA)														56								56 mm	0.9 meter	57.6 kg
M.S.Round ϕ 19 mm (3/4" DIA)																						14 mm	0.224 meter	0.55 kg
M.S.Round ϕ 25 mm (1" DIA)																		68				284 mm	4.6 meter	28.0 kg
M.S.Round ϕ 44 mm (1 3/4" DIA)																						186 mm	3.0 meter	26.5 kg

Total Nos. per Trainee	Total Nos. for 16 Trainees
1 No.	18 Nos.

Cheese Head Screws
M 5 x 15 mm

Tolerance ± 0.2




SCALE 1:1	FLANGE	MP/23/4.1.2/1
MAT.: MILDSTEEL		TURNING N




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER



Tolerance $\pm 0,1$
unless otherwise stated



25 _{f7}	- 20 - 41
32 _{g6}	- 9 - 25
8 _{N9}	0 - 36

SCALE 1:1

MAT.: MILD STEEL

SHAFT

Mp/2.3/4.1.2/2

TURNING IV



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING


PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER



Tolerance ± 0.1
unless otherwise stated.

65



SEQUENCE OF OPERATION

1. Hold workpiece on the rough machined $\phi 45$.
2. Machine the hole 25^{H7} , outside $\phi 120$ and step 72×4 .
3. Hold workpiece on a mandrel and finish the $\phi 44$.
4. Shape the keyway on a shaping machine.

SCALE 1:1

MAT: MILDSTEEL

From Ex.1

FLANGE

MP/2.1/4.1.2/3

TURNING IV



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING


PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER



Tolerance $\pm 0,1$
unless otherwise stated

66



SEQUENCE OF OPERATION

1. Chuck workpiece in three-jaw chuck.
2. Face one side.
3. Re-chuck, use distance bush to ensure parallel faces and face to thickness.
4. Turn step, drill and bore to $\phi 26$.
5. Turn internal groove.
6. Hold workpiece on a mandrel and turn outside diameter.

TOOLS

Bent roughing tool
Right hand side tool
Boring tool
Form grooving tool

SCALE 1:1

MAT MILDSTEEL

BEARING COVER

MP/2.1/4.1-2/4


TURNING IV





DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER



Tolerance $\pm 0,1$
unless otherwise stated



Note: Assemble the bearing with shaft ex.2, flange ex.3 and bearing covers ex.4
Check for smooth running.

SCALE 1:1

CAST IRON BEARING

Mp 2.3/4.1.2/5

MAT. CAST IRON

From 3.1.2/10


TURNING IV



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING


PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER



Tolerance ± 0.1
unless otherwise stated

68



$25_{f6} = \begin{matrix} -0.020 \\ -0.033 \end{matrix}$

SEQUENCE OF OPERATION

1. Mark and punch centre.
2. Drill centre hole with the help of drilling machine.
3. Chuck and set the lathe centre.
4. Machine a groove for the jaws of the steady rest.
5. Set the steady and remove the lathe centre.
6. Machine to the required dimensions.
7. Part off to a length of 100 mm.

SCALE 1:1

MAT. MILD STEEL

SHAFT

MP/2.3/4.2/5

TURNING IV



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING


PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

▽ (▽▽)

Tolerance ± 0.1
unless otherwise stated.

01



$$22^{H7} = \begin{matrix} +0.021 \\ 0 \end{matrix}$$

Check the hole 22^{H7} with a plug gauge.

SCALE 1:1

MAT CAST IRON

GEAR BLANK

MP/21/4.1.2/7



TURNING IV



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING





PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER



SCALE 1:1	MILLING HEAD BODY	MP/21/4.1.2/8
MAT MILDSTEEL		TURNING IV
 DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING PAK-GERMAN TECHNICAL TRAINING PROGRAMME		TURNER

Tolerance $\pm 0,1$



$\phi 18 k6$	+0.015 +0.002
$\phi 22 H7$	+0.021
$\phi 22 h6$	0 -0.013

SCALE 1:1

MAT. MILDSTEEL

PARTS OF
EXPANDING MANDREL

MP/21/4.1.2/9


TURNING IV



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

FAK GERMAN TECHNICAL TRAINING PROGRAMME



TURNER



Thread acc. to part No.1

3

4



1	Cheese head screw	5		M5 x 15
1	Cone washer	4		
1	Forcing nut	3		
1	Mandrel	2		
1	Taper shank	1		
Qty.	Denomination	Part-N.	Materil	Remarks

SCALE 1:1

MAT MILDSTEEL

EXPANDING MANDREL

MP/21/4.1.2/9a


TURNING IV







DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

TOLERANCE $\pm 0,2$ 
 unless otherwise stated



15 \varnothing_{h6}	0
15 \varnothing_{E8}	+0.059
15 \varnothing_{F7}	+0.034
	+0.016

1	CENTRE POINT (HARDENED)	3	CARBON STEEL
1	KNURLED NUT	2	MILDSTEEL
1	TAPER WITH THREAD	1	MILDSTEEL
QTY	Denomination	Part No	Material


SCALE 1:1	RUNNING CENTRE	MP/21/412/10
MAT:		TURNING IV




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING






PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER



SCALE 1:1	CIRCULAR CUTTER PART 1	MP/2.3/4.12/11
MAT: MILDSTEEL		TURNING IV

	DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING	TURNER
	PAK-GERMAN TECHNICAL TRAINING PROGRAMME	



SCALE 1:1

MAT. MILDSTEEL

CRANKSHAFT WITH BUSH

MP/23/4 12/12

TURNING IV



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

