

TRADE TRAINING I - II


T T C PROGRAMME


WELDER



GOVERNMENT OF THE PUNJAB
TECHNICAL EDUCATION VOCATIONAL TRAINING AUTHORITY
PUNJAB BOARD OF TECHNICAL EDUCATION
TRADE TESTING CELL, LAHORE


T.T.P. SERIES No. 29 Price Rs. 41/-






Cup

1




Spirit Bottle

2




Store Box

3



Sheet Metal Box

4



Dust Pan

5

TRADE TRAINING I

LAYOUT

MP/2.3/2.6.1

SHEET METAL



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER

MATERIAL REQUIRED

(Length given in millimeters)

TRADE TRAINING I

SHEET METAL


NO. 2.6.1/1 TO TEST	1.2	1.3	2.2	2.3	2.4	3.2	3.3	3.4	4.1	Test	Length per trainee	Total length for 16 trainees
Tinned Sheet 85 mm x 30 SWG	265										265	4.5 m
Tinned Sheet 90 mm x 30 SWG		90									90	1.5 m
Tinned Sheet 35 mm x 28 SWG		110									110	1.8 m
G.I. Sheet 85 mm x 28 SWG			200	120							320	5.25 m
G.I. Sheet 80 mm x 28 SWG					80						80	1.3 m
M.S. Pipe Nipple R 3/8" x 20 mm					1						1 No.	16 Nos.
Tinned Sheet 220 mm x 30 SWG						430					430	7 m
Tinned Sheet 144 mm x 30 SWG							170				170	2.75 m
Tinned Sheet 80 mm x 30 SWG								150			150	2.5 m
G.I. Sheet 45 mm x 28 SWG (2 pieces)									150		150	2.5 m
G.I. Sheet 45 mm x 28 SWG (2 pieces)									160		160	2.75
G.I. Sheet 250 mm x 28 SWG										380	380	6.25 m
G.I. Wire ϕ 3 mm									400	740	1140	18.25 m
M.S. Flat 30 x 3 mm 1 1/4" x 1/8"										220	220	3.75 m



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER




Material: tinned sheet 30 SWG


SEQUENCE OF OPERATIONS

1. Join parts 1 and 2 and solder the bottom joint as well as the folded joint.
Apply soldering fluid and tin solder sparingly to obtain a clean and proper joint.
2. Place the handle on the folded joint of the body and solder it.

CAUTION

Remove all remains of soldering fluid carefully with water after completing the work. The fluid contains acid and might cause corrosion of the tinned sheet.

SCALE 1:1	<h1>Cup</h1>	MP/2.3/2.6.1/11
MAT.TINNED SHEET		SHEET METAL
 DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING PAK-GERMAN TECHNICAL TRAINING PROGRAMME		<h2>WELDER</h2>




Material: tinned sheet 30 SWG


SEQUENCE OF OPERATIONS

1. Mark and cut the job according to the drawing.
2. Bead the upper edge and prepare the joint-edges for folding.
3. Round the job properly (bench number and bead outside!) and fold the joint as shown in the detail 2 : 1.

CAUTION

The tin layer on the sheet is thin and soft. Pencils should be used for marking therefore as steel scribers would damage the surface.

SCALE 1:1	Cup Development (Cylinder)	MP/23/2.61/1.2
MAT. TINNED SHEET		SHEET METAL
 DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING PAK-GERMAN TECHNICAL TRAINING PROGRAMME		WELDER



Material: tinned sheet 30 SWG

SEQUENCE OF OPERATIONS

1. Mark and cut both jobs according to drawing.
2. Bead the edges of the handle and bend it as shown in the assembly drawing No. 1.
3. Flange the bottom with the help of the edging tool and make sure that it fits precisely with the already completed part No. 1.

CAUTION

The soft tinned sheet must be handled with care in order to preserve the smooth and shining surface.

SCALE 1:1

MAT: TINNED SHEET

**Cup Development
(bottom and handle)**

MP/2.3/2.6.1/1.3


SHEET METAL



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



SEQUENCE OF OPERATIONS

1. Fit bottom and body together and fold the joint as shown in the detail.
2. Add parts No. 2 and 4 and solder all the joints.

SCALE 1:1

MAT. G.1 SHEET

Spirit Bottle

MP/23/261/21


SHEET METAL



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



SEQUENCE OF OPERATIONS

1. Mark and cut the job according to the drawing.
2. Prepare the joint edges for folding.
3. Round the job properly and fold the joint.
4. Prepare the body for joining it with the bottom by flanging its lower edge.

SCALE 1:1

MAT: G.I SHEET

Spirit Bottle Development


MP/2.3/2.6.1/2.2

SHEET METAL

DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



SEQUENCE OF OPERATIONS

1. Mark the development of the job on the sheet and shear it.
Mind the margins for the joints.
2. Bend the joint edges 90° and form the job to a cone.
3. Flange the upper and lower edge in the proper angles.

SCALE 1:1

MAT: G.I. SHEET

Spirit Bottle Development

MP/23/2.6/1/2.3



SHEET METAL



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



SEQUENCE OF OPERATIONS

1. Mark out the three diameters of part 3.
2. Cut to \varnothing 76 mm.
3. Bend the first 90° flange at 4 mm distance from the edge.
4. Cut the thread R $3/8$ " x 12 on part No. 4.
5. Cut part No. 4 to length 20 mm.

SCALE 1:1

MAT: G. SHEET

Spirit Bottle Development

MP/23/2.6.1/2.4



SHEET METAL




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



Detail X



Detail Y



Detail Z

SEQUENCE OF OPERATIONS

1. Remove the oxide layer from the spotwelding areas.
2. Fit parts 1 and 2 together as shown in detail "Y". Tackweld the corners (gas welding).
3. Fit part 3 as shown in detail "Z". Tackweld the corners.
4. Spotweld the box.
Distance of the spots mm;
amperage:
5. Finish the corners by filing.

1	Front part	3	Tinned sheet SWG 20
1	Main body	2	Tinned sheet SWG 20
1	Back part	1	Tinned sheet SWG 20
Qty.	Denomination	Part No.	Remarks/ Material


SCALE 1:2.5	STORE BOX	MPI/2.3/2.6.1/3.1
1/4" TINNED SHEET		SHEET METAL



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELSER



SEQUENCE OF OPERATIONS

1. Mark all lines forming the perimeter and check them.
Take the long (428 mm) edge as the reference line.
2. Cut out the piece, except for the lines a, b and c.
3. Cut at the lines a, b and c with the help of a chisel and finish with the flat file.
4. Mark the bending lines 1 and 1' at the rear, the lines 4 and 4' at the front side of the sheet.
5. Bend at lines 1 and 1' on the bending machine.
6. Bend at lines 2 and 3 (2' and 3') as shown in detail X of the following exercise sheet.
Use the special bending device provided by your instructor for this operation.
7. Bend at lines 4 and 4'.

SCALE 1:1

MP/2.3/2.6/3.2

MAT. TINNED SHEET

MAIN BODY OF STORE BOX


SHEET METAL



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



SEQUENCE OF OPERATIONS

1. Mark out the sheet (line 1 at the rear)
Punch all corners with the centre punch.
2. Cut along the outer lines (shearing machine).
3. Cut out the corners with the help of hand shears.
4. Cut the 2 mm-gap with the help of a hack saw.
5. Fold the sheet at marking line 1.
6. Bend the sheet at marking lines 2 and 2'.
7. Bend the job at marking line 3.

SCALE 1:25

MAT: TINNED SHEET

BACK OF STORE BOX

MP/23/2.6.1/3.3


SHEET METAL



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



SEQUENCE OF OPERATIONS

1. Mark all lines of the job.
(Line 1 at the rear.)
Punch the corners with a centre punch.
2. Cut along the outer lines (shearing machine).
3. Cut out the corners.
4. Bend at line 1.
5. Bend at lines 2 and 2'.
6. Bend at line 3. Mind the angle.

SCALE 1:25

MP/2,3/ 2,6,1/3,4

MAT: TINNED SHEET

FRONT OF STORE BOX



SHEET METAL



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME


WELDER




SEQUENCE OF OPERATIONS

Fit sides and body together and fold the joint as shown in the detail.

Apply soldering fluid and tin solder sparingly to obtain a clean and proper joint.

SCALE 1:1	SHEET METAL BOX	MP/2.3/2.6.1/4
MAT. G.I. SHEET		SHEET METAL
 DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING PAK-GERMAN TECHNICAL TRAINING PROGRAMME		WELDER



SEQUENCE OF OPERATIONS

- Mark out and cut the sheet.
- Wire the edges.
- Bend the job after preparing the joint edges for folding.
- Fit the side and body together and press the joint edges according to drawing.
- Apply the solder and clean it.

SCALE 1:2

MAT. G.I. SHEET

SHEET METAL BOX DEVELOPMENT

MP/2.3/2.6.1/4.1


SHEET METAL



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME


WELDER



SCALE 1:2
 MAT. G.I. SHEET

DUST PAN

MP/2.3/2.6.1/Test 1
 SHEET METAL




Pipe Clamp



Double Pipe Clamp


1



Hinged Pipe Clamp


3

2




Staple And Hasp

4



Hinge

5



Sliding Bolt Lock

6

TRADE TRAINING I

LAYOUT

MP/2.3/2.6.2

BENCH WORK



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER

MATERIAL REQUIRED

TRADE TRAINING I
BENCH WORK
NO. 2.6.2/ 1 TO 4

Total length
for 16
trainees

(Length given in millimeters)


	(Length given in millimeters)										Length per trainee	Total length for 16 trainees		
	1.1	1.2	2	3.1	3.2	3.3	4.1	4.2	4.3	4.4				
M.S. Sheet 26 x 3 m m	142	175	330										647	10.5m
M.S. Sheet 25.4 x 4.8 m m 1" x 3/16"				180 x 2 360	110	105							575	9.5m
Round "HD" Rivet Ø 8mm x 10 mm													1 NO	18 Nos
Round "HD" Rivet Ø 10 mm x 18 mm													1 NO	18 Nos
Countersunk Rivet Ø 5 mm x 6.5 mm													1 NO	16 Nos
M.S. Sheet 52 x 2 mm 13 SWG							81						81	1.3m
M.S. Round Ø 5 mm								275					350	5.75m
M.S. Sheet 37 x 2 mm 13 SWG												67	67	1.1m




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



2 Pieces



SCALE: 1:1

MAT: MILDSTEEL

PIPE CLAMPS

MP/2.3/2.6.2/1


BENCH WORK



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



SCALE: 1:1

MAT: MILDSTEEL

Double Pipe Clamp

MP/2.3/2.6.2/2


BENCH WORK



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



SCALE 1:1

MAT.:MILD STEEL

Hinged Pipe Clamp

MP/2-3/2.5.2/3

BENCH WORK







DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER

For all dimensions ± 2
unless otherwise stated.



1	Staple	4	St 37	ϕ 5 X 75
1	Base plate	3	Mild steel sheet	2 X 37 X 67
1	Hasp	2	St 37	ϕ 5 X 275
1	Hinge plate	1	Mild steel sheet	2 X 52 X 81


Nos.	DESCRIPTION	P.No.	MATERIAL	SIZES
SCALE: 1:1	STAPLE AND HASP			MP/2.3/26.2/4
MAT: MILDSTEEL				BENCH WORK



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



SCALE: 1:1
 MAT: MILDSTEEL

Hinge


MP/2.3/26.2/5
 BENCH WORK



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING
 PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER

For all dimensions $\pm 0,1$
unless otherwise stated.



SCALE: 1:1

MAT: MILDSTEEL

Sliding Bolt Lock

MP/2.3/26 2/6



BENCH WORK



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



1	Counter sunk rivet	8	Mild steel
1	Cylindrical head screw	7	M5 x 5
1	Flat spring	6	Spring steel
1	Handle	5	Mild steel
1	Bolt guide	4	Mild steel
1	Bolt guide	3	Mild steel
1	Locking bolt	2	Mild steel
1	Base plate	1	Mild steel
Qty.	Denomination	Part No	Material / Remarks

SCALE 1:1

SLIDING BOLT LOCK

MP/2.3/2.6.2/6.1


BENCH WORK



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING


PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER




Threading Exercise

1




Threading Exercise

2




Double Nipple

3




Water Pipe Installation

4




Water Pipe Installation

5




Pipe Bending

6




Pipe Bending

7



Branch Pipe

8



Pipe Bending

9

TRADE TRAINING I

LAYOUT

MP / 2.3 / 2.6.3

PIPE BENDING

DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



MATERIAL REQUIRED

TRADE TRAINING I
NO. 2.6.3/1 TO 9
PIPE BENDING


	(Length given in millimeters)									Total length for 16 trainees	
	1	2	3	4	5	6	7	8	9		
G.I PIPE ϕ $\frac{3}{4}$ "	32		52							84	1.4m
G.I PIPE ϕ 1"		34								34	0.6m
G.I PIPE ϕ $\frac{1}{2}$ "				755	1020					1775	28.4m
G.I ELBOW ϕ $\frac{1}{2}$ "				1	2					3 Nos	48 Nos
M.S PIPE ϕ $\frac{3}{4}$ "						525	525	1130	1200	3380	54m



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



SEQUENCE OF OPERATIONS

1. Check the quality of the pipe.
(Correct weld seam? Properly galvanized?
Diameter accurate?)
2. Thread the pipe, mind the length of the thread.
3. Cut the pipe and deburr it.

TOOLS REQUIRED

Measuring and marking tools

Threading die

Hacksaw

Flat file 200 x 3

Round file 200 x 3

CAUTION

NEVER THREAD WITHOUT OILING !

SCALE: 1:1

MAT: G.I PIPE

THREADING EXERCISE

MP/2,3/2,6,3/1


PIPE-WORK



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



SEQUENCE OF OPERATIONS

1. Check the quality of the pipe as done before.
2. Thread the pipe, mind the length of the thread.
3. Cut the pipe and deburr it.

TOOLS REQUIRED

Measuring and marking tools

Threading die

Hacksaw

Flat file 200 x 3

Round file 200 x 3

CAUTION

NEVER THREAD WITHOUT OILING !

SCALE: 1:1

MP/2.3/2.6.3/2

MAT: G.I PIPE

THREADING EXERCISE


PIPE-WORK



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



SEQUENCE OF OPERATIONS

1. Cut threads at the end of the pipe.
2. Mark the length of the nipple and cut it off.
3. Thread the other end of the nipple.

As it is too short to be chucked in the vice directly the nipple must be extended.

Use a suitable pipe with a socket at the end for this purpose.

SCALE: 1:1

MAT. G.I. PIPE

DOUBLE NIPPLE

MP/23/2.6.3/3


PIPE - WORK



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



SEQUENCE OF OPERATION

1. Check the material.
2. Cut the pipes to the length. Deburr the pipes and cut the thread.
3. Join the pipes with the bend.
4. Prepare the horizontal pipe in the same way and join it.
5. Point 'A' will be given by the Instructor.

CAUTION

The thread of fittings and pipes are slightly taper. If the thread is cut properly it should be possible to screw 80 % of the threaded portion into a fitting by hand.

SCALE: 1:1

MAT: G.I PIPE

WATER PIPE INSTALLATION

MP/23/26.3/4


PIPE - WORK



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



SEQUENCE OF OPERATION

1. Start the work from point 'A' given by the Instructor.
2. Prepare the 3 pieces in the proper sequence and join them with the bends.
3. Fix the pipe line with clamps on the wall.
4. Check finally if all dimensions correspond with the drawing.
5. Check the position of the last bend using pipe nipple and level.

CAUTION

The cut edges of the pipe must be deburred inside and outside.

SCALE: 1:1

MAT: G.I PIPE

WATER PIPE INSTALLATION

MP/2.3/2.6.3/5


PIPE - WORK



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



Material: 1 mild-steel pipe 3/4" x 500

SEQUENCE OF OPERATIONS

1. Fill the pipe with dry bending sand and close the ends with wooden plugs.
2. Mark the job.
3. Heat portion X and bend.
Take care that the weld-seam of the pipe is in the neutral line of the bend.

SCALE: 1:1

MAT. M.S.PIPE

Pipe Bending 1

MP/2.3/2.6.3/6


PIPE-WORK



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



Material: 1 mild-steel pipe 3/4" x 500

SEQUENCE OF OPERATION

1. Fill the pipe with bending sand and close the ends with wooden plugs.
2. Mark portion X for the upper bend.
3. Heat portion X and bend.
4. Let the first bend cool down before going on with the work
5. Mark portion X for the lower bend.
6. Heat portion X and bend.

SCALE: 1:1

MAT. M.S PIPE

Pipe Bending 2


MP/23/2.6.3/7

PIPE - WORK

DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



Material: the pipe bends from exercises No. 6 and 7

SEQUENCE OF OPERATIONS

1. Mark and cut the bends from the previous exercises according to the drawing.
2. Prepare the two T-branches as shown in the drawing.

The Exercise is to be completed during 3rd Semester Gas-welding course by carrying out the following operations:

3. Cutting holes for the T-branches with the help of the torch.
4. Joining all four pieces by gas-welding.

SCALE: 1:1

MAT: M.S PIPE

Branch Pipe

MP/23/2.63/8


PIPE-WORK



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



PIPE = \varnothing 3/4"
 OFFSET = 240
 RADIUS = 90
 B = 150

FOR 60° OFFSET BENDS

OFFSET = RUN X 1.732
 RUN = OFFSET X .577
 TRAVEL = OFFSET X 1.154
 SETBACK = RADIUS X .577
 LENGTH OF BEND = RADIUS X 1.047


FOR 90° CENTER BEND


$90^\circ - 60^\circ = 30^\circ$
 $30^\circ + 60^\circ = 90^\circ$ BEND
 SETBACK = RADIUS X 1.000
 LENGTH OF BEND = RADIUS X 1.571

SEQUENCE OF OPERATIONS

- Calculate the length of pipe according to the drawing and cut it.
- Mark the bending lay out on the plate or floor
- Mark the job.
- Fill the pipe with dry sand and close the ends with wooden plugs.
- Heat the first portion for 60° bend and bend it.
- Let the first bend cool down before going on with the work.
- Complete the job gradually.


SCALE 1:4	PIPE BENDING	MP/2.3/2.6.3/9
MAT. M.S PIPE		PIPE WORK

	DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING PAK-GERMAN TECHNICAL TRAINING PROGRAMME	WELDER
---	---	--------



Lap Joint

1




Butt Joint

2



Angle Joint

3




Double Joint

4



Lap Joint

5




Butt Joint

6




Butt Joint at an angle

7



Double Joint

8



Pipe Joint

9

TRADE TRAINING I

LAYOUT

MP/2.3/2.6.4

SOLDERING/BRAZING



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER

MATERIAL REQUIRED

TRADE TRAINING I
SOLDERING/BRAZING
NO:2.6.4/1 TO 9

(Length given in millimeters)

	1	1a	1b	1c	2	3	4	5	6	7	8	9	Length per trainee	Total length for 16 trainees
M.S. Sheet 56x1 2 1/4"x19 SWG 2 pieces	62 x 2				62 x 2	62 x 2							372	6m
Stainless Steel 56x1 2 1/4"x19 SWG 2 pieces	62 x 2												124	2m
Copper Sheet 56x1 2 1/4"x19 SWG 2 pieces		62 x 2	62 x 2										124	2m
Brass Sheet 56x1 2 1/4"x19 SWG 2 pieces				62 x 2									124	2m
M.S. Sheet 72x1 2 7/8" x 19 SWG 3 pieces							62 x 3						186	3m
M.S. Sheet 52x3.2 2 1/8" x 1" 3 pieces								122 x 3	122 x 3	122 x 3			1099	18m
M.S. Sheet 75x3.2 3"x1" 3 pieces											122 x 3		366	6m
M.S. Sheet 16x2 5/8" x 13 SWG												90	90	1.5m
M.S. Pipe ϕ 3/4"												65	65	1m




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER


Blow lamp

The blow lamp is primarily used for larger workpieces such as large cable lugs for tinning and soldering.



Tinning bath

The tinning bath is used for mass production purposes. It can be heated either with open flame or electrically.



Solder iron

Electrically heated and used for soldering of small wires in radios or printed circuits. 16 upto 30 Watt



60 upto 150 Watt



200 upto 300 Watt



Note:

The solder iron must be clean and well tinned.

TRADE TRAINING I

SOLDERING APPLIANCES

MP/2.3/2.6.4/a

Soldering



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

Means for cleaning soldering irons (tinned end of copper bit)

Description and Use

Example

Linen rag
for wiping

Wire brush
for removing scale or oxide layers

Ammonium chloride block
for cleaning soldering iron chemically

File
for smoothing out burnt areas; major damages to copper bit to be repaired by forging


Means for cleaning areas to be soldered or brazed. Initiation of the soldering or brazing process requires the area to be perfectly bright

The area to be soldered or brazed may require cleaning both before-hand and afterwards:


- mechanical cleaning with tools
- chemical cleaning with acids or solvents

The choice of the cleaning means depends on the size, number and material of the workpieces and on the type of flux used.

After soldering most cleaning acids and fluxes must be carefully washed off to prevent corrosion e.g. neutralising acids and alkalis.



wire brush for cleaning



ammonium chloride

single cut file



triangular scraper



wire brush



blade scraper



file



TRADE TRAINING I

EQUIPMENT FOR CLEANING SOLDERING IRONS AND SOLDERING AREAS

MP/2.3/2.64/b

SOLDERING



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

Maintenance and Tinning of the Soldering Iron is necessary for guaranteeing a satisfactory transition of the heat stored by the iron to the workpiece. The iron must have a smooth and well tinned soldering surface. All impurities and defects are detrimental to and delay the transition of the heat. More frequent cleaning, re-finishing and retinning are therefore required.

Impurities

e.g., burnt flux, etc. must be:

1. wiped off with a linen cloth or
 2. removed with a wire brush
- while the soldering iron is warm.

Damage to the copper section of the soldering iron is caused by the gradual dissolution of the copper by the solder (corrosion, scouring).

Minor Damage

- A. Refinish soldering surface of wedge and side faces.
- B. Heat and tin soldering iron.

Major Damage


Re-forgage copper section. Further refinishing as under steps A and B.

Interchangeable copper sections must be descaled periodically.

The Tinning of the soldering surface can be effected, depending on the type and use of the iron, by one of the following techniques:

1. Rub soldering surface on ammonia stone with the addition of solder.
2. Apply flux on soldering surface (no soldering solution or acid) and add and distribute solder.
3. Apply soldering paste with sticks and distribute.
4. Spread tubular solder on soldering surface.

Care must be taken, that the soldering iron has the proper temperature.



What is Tinning?


Tinning is a process for coating the surface of a workpiece with an insoluble layer of tin (solder).

Technique

In tinning the workpiece and the tin (solder) are heated to the required "working temperature" so that the solder can "flow" and "wet" the surface of the workpiece, i.e., that solder and workpiece can be bonded insolubly.

Excessive solder can be removed either by brushing or shaking off.

Tinning is also used as a separate step in all soldering of non-tinned parts.




Tinning with Flame

Requirements

A proper tin coating can be obtained only if

1. the workpiece is free of all impurities and oxydations (combinations of metal with the oxygen of the air), i.e., it must be metallicly pure;
2. no fresh oxydations can occur during tinning, these can generally be prevented by using Fluxes; and
3. workpiece and tin have been heated to the required working temperature.




Tinning with Soldering Iron

Purpose and Use

Tinning is used for preparing workpieces for soldering, or to protect workpieces (especially sheet metal) from corrosion.


Note:

In these papers, tinning is described in as far as it is used manually as a preliminary to soldering.



Tinning in the Tin Bath






S.NO	THICKNESS	MATERIAL	FLUX
1	1mm	Mild Steel	
1a	1mm	Stainless.S.	
1b	1mm	Copper	
1c	1mm	Brass	

SEQUENCE OF OPERATIONS

- Deburr, straighten and clean the sheet metal plates.
- Mark the plates.
- Add flux and arrange the plates according to the drawing.
- Solder the lap joint.
- Clean the soldered joint.



43


SCALE	LAP JOINT	MP12.313.5.411
MAT. MILD STEEL		Soldering



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER




SEQUENCE OF OPERATION

1. Take the material from Exercise Lap Joint and use the untinned side face for the butt joint.
2. Clean the sheet metal if necessary.
3. Leave a soldering gap of 0.2 mm between the sheet metal pieces.
4. Add flux and solder the butt joint.
5. Clean the butt joint.

TOOLS AND MATERIALS

Soldering iron
 Asbestos plate
 Soldering paste
 Tubular solder
 Wire brush
 Emery paper



44
 TRADE TRAINING I

BUTT JOINT



MP/23/2.64/7

Soldering




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME



SEQUENCE OF OPERATION

1. Take the material from Exercise Butt Joint, clean off any tin and bend one sheet metal plate according to drawing.
2. Tin the parts to be soldered.
See instr. sheet No. 1.5.2/6.
3. Tack the angle with solder to prevent shifting while soldering.
4. Add flux and solder the workpiece by moving the solder iron slowly forward.
5. Clean the workpiece.



TOOLS AND MATERIALS

Soldering iron
 Asbestos plate
 Soldering paste
 Tubular solder
 Wire brush
 Emery paper

TRADE TRAINING 1

TINNING AND SOLDERING OF AN ANGLE


MP/2.3/2.5.4/3

Soldering



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME



SEQUENCE OF OPERATIONS

1. Cut strip 15mm and deburr the material
2. Clean the joined surfaces
3. Fit the parts in the joint
4. Lay up the pieces, add flux and solder

Note:

The 15mm cover strip must be concentrically over the joint.

SCALE 1:1

MAT-M.S SHEET

DOUBLE JOINT


ME-12312-E-474

Soldering



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

STATE OF HARYANA TECHNICAL TRAINING PROGRAMME



A few examples for training in seam soldering as a suggestion for the selection of workpieces of a productive or unproductive nature for the systematic instruction in seam soldering.

TRADE TRAINING I

SUGGESTIONS FOR FURTHER PRACTICE


MP/2.3/2.6.4/4.1

SOLDERING

DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING


PAK-GERMAN TECHNICAL TRAINING PROGRAMME





SEQUENCE OF OPERATION

1. Cut, straighten and de-burr the material.
2. Clean the parts thoroughly.
3. Add flux and arrange according to sketch.
4. Heat up to working temperature.
5. Add spelter.
6. Clean the workpiece (no flux should remain on it).



DIRECTIONS

1. The area which is to be brazed must be clean (no oxide layer).
2. After cleaning don't touch the area with your hands.
3. Don't overheat the workpiece and the flux, use a "soft" flame (slight excess of acetylene).

SCALE 1:1

MAT. MILD STEEL

LAP JOINT


MP/2.3/2.6.4/5

BRAZING



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME



SEQUENCE OF OPERATION

(Refer to previous exercise No. 6)

Note: Brazing requires repeated exercise.

Therefore the joint should be cut and re-brazed again until proper joints are achieved.

The workpiece sizes are only suggested, any suitable scrap material can be used.

SCALE 1:1

MAT. MILD STEEL

BUTT JOINT


MP/2.3/2.6.4/5

BRAZING



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME



SEQUENCE OF OPERATION

1. File the bevelled edge on both parts.
2. Join two parts by brazing as explained in exercise No. 6.

SCALE 1:1

MAT. MILD STEEL

BUTT JOINT AT AN ANGLE


MP/2.3/2.6.4/7

BRAZING



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME



SEQUENCE OF OPERATION

1. Prepare the workpieces for brazing (cut, straighten, deburr and clean).
2. Add flux and arrange according to drawing.
3. Braze.
4. Cut by means of hand hacksaw along the and check for full penetration of the spelter.
5. Repeat this exercise several times till a satisfactory skill is achieved.

SCALE 1:1

MAT. MILD STEEL

DOUBLE JOINT


MP/2.3/2.6.4/8

BRAZING




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME



2



SEQUENCE OF OPERATION

1. Cut the two pipes to length.
2. Calculate the length of part 2 and prepare it accordingly.
3. Clean all parts with emery paper.
4. Add flux and braze the joint.
5. Clean of the remaining flux.

SCALE 1:1

MAT. M.S. PIPE

PIPE JOINT


MP/2.3/2.6.4/9

BRAZING



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME



A few examples for training in brazing jobs of increasing difficulty as a suggestion for the selection of workpieces of a productive or unproductive nature for the systematic instruction in brazing.

SUGGESTIONS FOR FURTHER PRACTICE


MP/2.3/2.6.4/9.1

BRAZING

DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING


PAK-GERMAN TECHNICAL TRAINING PROGRAMME






Straight Bead

1




Corner Joint

2




T Joint

3



Square Butt Joint

4



Square Butt Joint

5




Square Butt Joint

6



Square Butt Joint

7



Square Butt Joint

8

TRADE TRAINING I

LAYOUT

MP 2.3/2.6.5

GAS WELDING I



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER

MATERIAL REQUIRED

(Length given in millimeters)


TRADE TRAINING I GAS WELDING I NO. 2.6.5/1 TO 8	1	2	3	4	5	6	7	8	Length per trainee	Total Length for 16 trai- nees.
M.S. Flat 100x2.04 4" x13 SWG	200								200	3.25m
M.S. Flat 37 x2.04 1½" x13 SWG		800	400	800	800	800	800		4400	70.5m
M.S. Flat 50x2.04 2" x13 SWG			400						400	6.5m
M.S. Pipe Ø 2½"								150	150	2.5m



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



Ex. No.	Thickness t			Space mm	Method	Torchsize mm	Rod ϕ mm
	mm	SWG	inch				
1	2.04				Leftward		

SEQUENCE OF OPERATIONS

- Draw the straight lines on the job.
- Set the neutral flame.
- Keep the distance about 3mm between end of the inner cone and job surface at the right hand edge.
- Establish the weld pool, add filler rod.
- Start the progressive leftward movement of blowpipe and filler rod.
- Slowly withdraw the flame near the left hand edge of the sheet.

CAUTION

- Keep the end of the filler rod within the flame envelop but not in the hot portion near the cone.
- Apply correctly speed of the travel and the filler rod, the deposition will be of even ripple and uniform width.


SCALE	Straight Bead (FLAT)	MP/2.3/2.6.5/1
MAT. MILD STEEL		GAS WELDING



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME


WELDER




Ex. No.	Thickness t			Space mm	Method	Torchsize mm	Rod ϕ mm
	mm	SWG	inch				
2	2.04				Leftward		



Be sure that the tip is always tight in the torch.
Loose tips cause flashback.



Top View



End View

Position of torch and rod when welding a corner weld.


SCALE	Corner joint (HORIZONTAL)	MP/2.3/26.5/2
MAT. MILD STEEL		GAS WELDING



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER





Ex. No.	Thickness t			Space mm	Method	Torchsize mm	Rod ϕ mm
	mm	SWG	inch				
3	2.04				Leftward		



Errect standing gas cylinders have to be prevented from falling down.

Position of torch and rod when welding a tee joint in horizontal position.




SCALE	T joint (HORIZONTAL)	MP/2.3/26.5/3
MAT. MILD STEEL		GAS WELDING



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER





Ex. No.	Thickness t		Space mm	Method	Torch size mm	Rod ϕ mm
	mm	SWG				
4	2.04			Leftward		



Always wear goggles while welding the ultraviolet rays may lead to blindness, goggles absorb them.

Position of torch and rod when welding a square butt joint in flat position.



SCALE

MAT. MILD STEEL

Square butt joint (FLAT)

MP12.3/26.5/4


GAS WELDING



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER




Ex. No.	Thickness t			Space mm	Method	Torchsize mm	Rod ϕ mm
	mm	SWG	inch				
5	2.04				Leftward		


- If the heat build up becomes excessive, remove the point of the cone temporarily from the weld.

Position of torch and rod when welding a square butt joint in horizontal position.

End View



Front View




SCALE	Square butt joint (HORIZONTAL)	MP/2.3/26.5/5
MAT. MILD STEEL		GAS WELDING



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING


PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



Ex. No.	Thickness t		Space mm	Method	Torchsize mm	Rod ϕ mm
	mm	SWG				
5	2.04	-		Leftward		

Position of torch and rod when welding a square butt joint vertical upward position.




SCALE	Square butt joint (VERTICAL UPWARD)	MP/2.3/2.6.5/6
MAT. MILD STEEL		GAS WELDING





DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



Ex. No	Thickness		Space mm	Method	Torchsize mm	Rod ϕ mm
	mm	SWG				
7				Leftward		



Sequence of operation

1. Set up the pieces, make sure that the gap is equal all over.
2. Tack the pieces.
3. Clamp the job.
4. Weld the seams in overhead position.

SCALE:

MAT: MILDSTEEL

SQUARE BUTT JOINT (OVER HEAD)

MP/2.3/2.6.5/7


GAS WELDING



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING


PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



Ex. No.	Thickness		Space mm	Method	Torchsize mm	Rod ϕ mm
	mm	SWG				
8		-		Leftward		

Position of the torch and rod when leftward-welding on pipes in fixed position.


















SCALE:	SQUARE BUTT JOINT ON PIPE (FL/V/OH)	MP/2.3/2.6.5/8
MAT: MILDSTEEL		GAS WELDING



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER

			
Corner Joint	Square Butt Joint	Single V Butt Joint	Square Butt Joint
1	2	3	4
			
Single V Butt Joint	Single V Butt Joint	Square Butt Joint	Pipe V Butt Joint
5	6	7	8
			
Single V Butt on Pipe	T Joint Equal Dia	Lateral Equal Dia	Y Joint
9	10	11	12
			
Single V Butt Joint	Square Butt Joint	Torch Cutting	
13	14	15	

TRADE TRAINING II

LAYOUT

MP/2.3 / 3.6.1

GAS WELDING II



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER

MATERIAL REQUIRED

(Length given in millimeters)

TRADE TRAINING II
GAS WELDING
NO. 3.6.1/1 TO 15.1


	1	2	3	4	5	6	7	8	9	10	11	12	13	14	14a	14b	15	15.1	Length per trainee	Total length for 16 trainees
M.S.Flat 31x3 1 1/4" x 1/8"	800	800	800	800		800													3200	51.25m
M.S.Flat 31x4.67 1 1/4" x 3/16"		800			800	800													2400	38.5m
M.S.Pipe ϕ 3"								150	150										300	5.0m
M.S.Sheet 100x2.04 4" x 13 SWG										205	205	620							1030	16.5m
M.S.Sheet 150x2.04 6" x 13 SWG										205	205								410	6.75m
Cast Iron 40x10 1 5/8" x 3/8"													800						800	13 m
Al-Sheet 31x2.04 1 1/4" x 13 SWG														800					800	13 m
Copper Sheet 31x2.04 1 1/4" x 13 SWG															800				800	13 m
Brass Sheet 31x2.04 1 1/4" x 13 SWG																800			800	13 m
M.S.Flat 100x10 4" x 3/8"																	200	200	400	6.5m



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME


WELDER




Ex. No.	Thickness t			Space mm	Method	Torchsize mm	Rod ϕ mm
	mm	SWG	inch				
1	3				Rightward		

Position of torch and rod when welding a corner joint in flat position

Blow pipe and filler rod



End view



Front view


SCALE	Corner joint (FLAT)	MP/2.3/3.6.1/1
MAT. MILD STEEL		GAS WELDING



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME


WELDER



Ex. No.	Thickness t			Space mm	Method	Torchsize mm	Rod ϕ mm
	mm	SWG	inch				
2	3				Rightward		

- Ensure adequate heating of the parent metal. Melt the tack and plate to establish the weld pool before adding filler metal.

Position of torch and rod when welding a square butt joint in flat position.



root bead of 1.3 mm is necessary for a strong seam.


SCALE	Square butt joint (FLAT)	MP/2.3/3.6/1/2
MAT. MILD STEEL		GAS WELDING





DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



Ex. No.	Thickness		t	Space	Method	Torchsize	Rod ϕ
	mm	SWG					
3					Rightward		



Fill in the numbers concerned:

- Correct root bead
- Undercut
- Poor root bead
- Smooth seam

SCALE:

MAT: MILDSTEEL

SINGLE V BUTT WELD (FLAT)

MP/2.3/3.6/1/3


GAS WELDING



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING



PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



Ex. No.	Thickness t			Space mm	Method	Torchsize mm	Rod ϕ mm
	mm	SWG	inch				
4	3				Rightward		

Position of torch and rod when welding square butt joint in horizontal position.




SCALE	Square butt joint (HORIZONTAL)	MP/2.3/3.6/1/4
MAT. MILD STEEL		GAS WELDING



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING


PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



Ex. No.	Thickness t		Space mm	Method	Torchsize mm	Rod ϕ mm
	mm	SWG				
5	4.67			rightward		

Position of torch and rod when welding single V butt joint in horizontal position




SCALE	Single V Butt Joint (HORIZONTAL)	MP/2.3/3.6.1/5
MAT. MILD STEEL		GAS WELDING






DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



Ex. No.	Thickness mm	Thickness SWG	t inch	Space mm	Method	Torchsize mm	Rod ϕ mm
6					Rightward		



Position of torch and rod when upward welding on a single-V-butt joint.

The puddle

Movement of rod

SCALE:

MAT.: MILDSTEEL

SINGLE V BUTT WELD

(VERTICAL)
UPWARD

MP/2.3/36.1/6


GAS WELDING



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING



PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



Ex. No.	Thickness t			Space mm	Method	Torchsize mm	Rod ϕ mm
	mm	SWG	inch				
7	3				Rightward		

- Use the same semi-circular motion of the torch as previously described. To help keep the puddle shallow, move the filler rod slowly in circular or swinging motion.




SCALE	Square butt joint (OVER HEAD)	MP/2.3/3.6/7
MAT. MILD STEEL		GAS WELDING




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER




Ex. No	Thickness t		Space mm	Method	Torchsize mm	Rod ϕ mm
	mm	SWG				
8						



Sequence of operation

1. Set the pieces (space !)
2. Tack the pieces.
3. Clamp the job in vertical position.
4. Weld the seam in horizontal position.



Move around the joint while welding.
Do not turn the pipe.


SCALE:	PIPE V BUTT WELD (HORIZONTAL) FIXED	MP/2.3/3.6.1/ 8
MAT: MILDSTEEL		GAS WELDING



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING


PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WEIDER



Ex. No.	Thickness t			Space mm	Method	Torchsize mm	Rod ϕ mm
	mm	SWG	inch				
9					rightward		

- Blowpipe nozzle and filler rod are both held at an angle of 45° .
- Bring the flame cone immediately in front of the lower edge of the molten pool and move parallel to the joint edge without any sideways movement of the blowpipe.




SCALE	Single V Butt Joint on Pipe FIXED	MP/2.3/3.6.1/9
MAT. MILD STEEL		GAS WELDING



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER





Ex. No.	Thickness t			Space mm	Method	Torchsize mm	Rod ϕ mm
	mm	SWG	inch				
10					Leftward		

SEQUENCE OF OPERATION

- Mark out the development on the sheet and cut it.
- Round the job properly.
- Fit part No.1 and 2 together and tack the job with gap.
- Deposit the bead and obtain full penetration.

Caution.
Do not
turn the
pipe.




SCALE	T joint equal dia	MP/2.3/3.6/1/10
MAT. MILD STEEL		GAS WELDING



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME



WELDER



Ex. No.	Thickness t		Space mm	Method	Torchsize mm	Rod ϕ mm
	mm	SWG				
11				Leftward		

SEQUENCE OF OPERATIONS

- Mark out the development of the job and cut it.
- Round the job properly.
- Fit part No.1 and 2 together and tack the job with no gap.
- Deposit the bead and obtain full penetration.




SCALE	Lateral (EQUAL DIA)	MP/2.3/3.6.1/11
MAT. MIL. STEEL		GAS WELDING



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME


WELDER



Ex. No.	Thickness t		Space mm	Method	Torchsize mm	Rod ϕ mm
	mm	SWG inch				
12				Leftward		

SEQUENCE OF OPERATIONS

- Mark out the development on the sheet and cut it.
- Round the job properly.
- Fit part No.1,2 and 3 together and tack the job with gap.
- Deposit the bead and obtain full penetration.




SCALE	Y - Joint (EQUAL DIA)	MP/2.3/3.6.1/12
MAT. MILD STEEL		GAS WELDING



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



Sequence of operation


1. The edges of both pieces are to be bevelled in the machine section.
2. Preheat one piece up to 550°C and weld a 4 mm thick layer on side "A".
3. Cover the piece under dry and warm sand after welding.
4. Repeat operations 2 and 3 at the second piece.
5. Place the two pieces according to drawing.
6. Preheat both pieces equally up to 550°C .
7. Make a strong tack-weld on the right end of the seam.
8. Weld a continuous seam from left to right.
9. Cover the job immediately after welding with dry and warm sand to ensure slow cooling.
10. Clean the piece and punch your bench number.


TOOLS AND WELDING MATERIAL REQUIRED

1. Torch size 6-9 (9-14).
2. Cast iron filler rod 6-8 mm.
3. Cast iron flux.

MATERIAL

Cast iron


SCALE	CAST IRON JOINT	MF/2.3/3.51/13
MAT. CAST IRON		GAS WELDING
 DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING		WELDER
PAK-GERMAN TECHNICAL TRAINING PROGRAMME		




Ex. No.	Thickness		t inch	Material	Space mm	Methode	Torchsize mm	Rod ϕ mm
	mm	SWG						
14	2			Al-Sheet		Leftward	2 - 4	2
14a	2			Cu-Sheet		Leftward	4 - 6	2
14b	2			Brass Sheet		Leftward	2 - 4	2

Sequence of operation (14)


1. Mark out and cut the strips to size 200 x 20 (Aluminium).
2. Straighten the pieces (use a wooden hammer).
3. Set up the strips and apply flux
(an equal gap is essential for a good seam).
4. Adjust the torch to a "soft flame" (slightly C_2H_2 excess).
5. Tack weld according to the sketch.
6. Preheat to about $550^{\circ}C$.
7. Weld the seam.
8. Remove the remaining flux by
 - a. washing in hot water and brush with a wire brush.
 - b. washing in diluted nitric acid (10 %).
 - c. washing in water.
 - d. drying.



SCALE:	SQUARE BUTT JOINT (FLAT)	MP/2.3/361/14
MAT:		GAS WELDING
 DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING PAK-GERMAN TECHNICAL TRAINING PROGRAMME		WELDER

Sequence of operation (14a)

1. Mark out and cut the strips to size 200 x 20 (copper).
2. Straighten the pieces (use a wooden hammer).
3. Set up as shown in the sketch.
Don't tack the pieces. Put a small wedge between the strips.
4. Apply flux.
5. Adjust the flame exactly neutral.
Exceeding C_2H_2 results in pores.
Exceeding O_2 results in an oxidized seam.
6. Start welding at point 'A' in direction '1'.
Move the wedge as the weld progresses.
7. After completion start at point 'A' again and weld in direction '2'.
8. Remove the remaining flux.
9. Heat up the workpiece to about $700^{\circ}C$ and hammer the seam with a spherical hammer to increase the tensile strength.



Sequence of operation (14b)

1. Mark out and cut the strips to size 200 x 20 (brass).
2. Straighten the pieces (use wooden hammer).
3. Set up the strips and apply flux.
4. Adjust the flame
25 % up to 50 % surplus of oxygen
is required to prevent evaporation
of the zinc.
5. Tack weld and weld the seam.
6. Remove the remaining flux.

SCALE:

MAT: COPPER BRASS

SQUARE BUTT JOINT (FLAT)

MP/2.3/3.6/1/14a_14b

GAS WELDING

DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING



PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER




SEQUENCE OF OPERATIONS

1. Mount the torch guide on the head of the cutting torch in such a way that the distance between workpiece and torch is about 5 mm.
2. Open Oxygen Valve.
3. Open Acetylen valve and light torch.
4. Adjust flame - Open cutting valve and re-adjust flame - if necessary - close cutting valve.
5. Heat starting point to bright red and open cutting valve.
6. Rate of travel.
 - (1) Correct speed.
 - (2) Too slow.
 - (3) Too fast.



SCALE	TORCH CUTTING	MP/2.3/3.6.1/15
MAT MILD STEEL		GAS CUTTING
DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING		WELDER
PAK-GERMAN TECHNICAL TRAINING PROGRAMME		



SEQUENCE OF OPERATIONS

1. Mark out according to sketch A and B.
2. Centre punch the marking line.
3. Adjust torch guide for vertical cut.
4. Slightly open the oxygen valve.
5. Open Acetylen valve.
6. Light torch and adjust flame.
7. Open cutting valve correct flame (if necessary).
8. Close cutting valve.
9. Set torch at the edge of the 1st marking line.
10. Heat to bright red.
11. Open cutting valve.
12. Pull torch with uniform speed along the marking line.
13. Close cutting valve.
14. Repeat operation 9-13 on marking line 2-4.
15. Close acetylen valve.
16. Close oxygen valve.
17. Adjust torch guide for 30° bevel cut.
18. Repeat operation 4-16 on workpiece B.

SCALE

MAT. MILD STEEL

TORCH CUTTING

MP/2.3/3.6.1/15.1



















GAS CUTTING



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER

 Straight Bead	 Wearing	 T Joint	 Square Butt Joint
1 → 2	2	3	4
 Single V Butt Joint	 Corner Joint	 Single V Butt joint	 Fillet Weld
5	6	7	8
 Single V Butt Joint	 T Joint	 Single V Butt Joint	 Pipe on Plate
9	10	11	12
 Build up weld	 Pipe on Plate	 Single V Butt Joint on Tube	 Single V Butt Joint
13	14	15	16
	 T Joint	 Single V Butt joint	
	17	18	

TRADE TRAINING II

LAYOUT

MP/2-3/3-6-2

ARC WELDING



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER

MATERIAL REQUIRED

(Length given in millimeters)

TRADE TRAINING II
ARC WELDING
NO.3.6.2/1 TO 18

	(Length given in millimeters)																		Total Length For 16 trainees.	
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18		
M.S.Flat 100x6.35 4" x 1/4"	200																		200	3.25m
M.S.Flat 31 x 6.35 1 1/2" x 1/4"		400		800			400	400	400										2000	32.5m
M.S.Flat 50x6.35 2" x 1/4"		400					400	400											1200	19.25m
M.S.Flat 31x2.93 1 1/2" x 11 SWG			800																800	13 m
M.S.Flat 37x6.35 1 1/2" x 1/4"				800															800	13 m
M.S.Flat 37x9.52 1 1/2" x 3/8"						800		800		800									2400	38.5m
M.S.Flat 75x4.76 3" x 3/16"											75	75	75						225	3.75m
M.S.Pipe ø 2"											30	30	30						90	1.5 m
S.S.Sheet 31x6.35 1 1/2" x 1/4"																400			400	6.5 m
M.S.Pipe ø 3"															100	100			200	3.25m
S.S.Sheet 50x6.35 2" x 1/4"																400			400	6.5 m
S.S.Sheet 37x9.52 1 1/2" x 3/8"																	800		800	13 m


Use material of Ex.No. 1



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER





Ex.No.	Thickness t		Space mm	Electrode ϕ		Name of Electrode	Amps recommended	Amps. used.
	mm	SWG		mm	SWG			
1	6.35		-	3.25				


SEQUENCE OF OPERATIONS

- Mark the straight lines on the job.
- Strike the electrode as close as possible to the joint where the weld is started.
- Deposit the continuous bead from left to right end without weaving.
- Do not throw away a stub end which is longer than 35-45mm.

POSITION OF ELECTRODE



SCALE	STRAIGHT BEAD (FLAT)	MP/2.3/3.6.2/1
MAT. MILD STEEL		ARC WELDING





Ex. No.	Thickness t			Space mm	Electrode ϕ		Name of Electrode	Amps recommended	Amps used
	mm	SWG	inch		mm	SWG			
2	6.35			-	3.25 4.00				

SEQUENCE OF OPERATIONS

- Use any one type of weaving motion to fill the space (preferably crescent motion).
- Make certain that the straight beads are covered half of the width by weaving.

POSITION OF ELECTRODE



CRESCENT MOTION

Note. Use material of Ex.No.1.


SCALE	WEAVING (FLAT)	MP/2.3/3.6/2/2
MAT. MILD STEEL		ARC WELDING



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME


WELDER



Ex.No.	Thickness t		Space mm	Electrode ϕ		Name of Electrode	Amps recommended	Amps. used.
	mm	SWG		inch	mm			
3	3	8	-	4	mm			

SEQUENCE OF OPERATIONS

- Set up and tack the pieces.
- Deposit the first bead with sliding likely along the edges of the joint.
- Deposit the second bead which partially covers the first pass.
- Deposit the third bead which covers the first pass and part of the second pass.



FILL IN THE NUMBERS CONCERNED

- Proper fusion
- Rolled edges
- Undercut
- Correctly applied seams
- Leg length


SCALE	T JOINT (HORIZONTAL)	MP/2.3/3.6.2/3
MAT. MILD STEEL		ARC WELDING



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER





Ex. No.	Thickness t		Space mm	Electrode ϕ		Name of Electrode	Amps recommended	Amps. used.
	mm	SWG		mm	SWG			
4	4mm		2-3	3.25				

SEQUENCE OF OPERATIONS

- Tack the pieces with root gap about 3mm.
- Strike the electrode as close as possible to the joint where the weld is started.
- Move the electrode steadily forward with slightly weaving motion.
- Make sure that the penetration is fully obtained.

POSITION OF ELECTRODE




SCALE	SQUAR BUTT JOINT (FLAT)	MP/2.3/3.6/2/4
MAT. MILD STEEL		ARC WELDING



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



Ex. No.	Thickness t		Space mm	Electrode ϕ		Name of Electrode	Amps recommended	Amps. used
	mm	SWG		mm	SWG			
5	9		2-3	2.5 3.25				

SEQUENCE OF OPERATIONS

- Bend the parts about 10° before starting the weld to compensate the contraction-action of the weld.
- Move the electrode smoothly forward in the joint with weaving motion.
- Try to keep the pear shaped hole in the root.
- Avoid passing the electrode against the face of the joint.

Work pieces
before welding



Work pieces
after welding



SCALE

SINGLE BUTT JOINT (FLAT)

MP/2.3/3.6.2/5

MAT. MILD STEEL


ARC WELDING





DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



Ex. No.	Thickness t		Space mm	Electrode ϕ		Name of Electrode	Amps. recommended	Amps. used
	mm	SWG		inch	mm			
6			1/4		10/8			



Fill in the numbers concerned

- 1 Rolled edge
- 2 Correct seams
- 3 Proper fusion
- 4 Undercut


SCALE:	CORNER JOINT (horizontal)	MP/2.3/3.6.2/6
MAT: MILDSTEEL		ARC WELDING



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER




Ex. No.	Thickness t		Space mm	Electrode ϕ		Name of Electrode	Amps. recommended	Amps. used
	mm	SWG		inch	mm			
7			$\frac{3}{8}$		10			

Movement of electrode for the required layers




Movement for root-bead



Movement for second layer



Movement for top-layer



SCALE:

MAT MILDSTEEL

SINGLE V BUTT JOINT (VERTICAL UPWARD)

MF/2.3/3 5 2/7


ARC WELDING



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME


WELDER




Ex. No.	Thickness t			Space mm	Electrode ϕ		Name of Electrode	Amps recommended	Amps. used
	mm	SWG	inch		mm	SWG			
8			3/16	-		10			

POSITION OF ELECTRODE

- When welding downwards, use only straight beads.
- Weaving-motion produces a heavy puddle, which cannot be controlled and will finally drop down.



WORK ANGLE



TRAVEL ANGLE


SCALE	FILLET WELD (vertical downward)	MP/2.3/3.6.2/8
MAT. MILD STEEL		ARC WELDING




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



Ex. No.	Thickness t		Space mm	Electrode Ø		Name of Electrode	Amps recommended	Amps used
	mm	SWG		inch	mm			
9			3/8"					



93


SCALE:	S.V - BUTT JOINT (HORIZONTAL)	MP/23/3.6.2/9
MAT: MILDSTEEL		ARC WELDING





DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



Ex. No.	Thickness t			Space mm	Electrode Ø		Name of Electrode	Amps recommended	Amps. used
	mm	SWG	inch		mm	SWG			
10			1/4"			10/8			



Fill in the numbers concerned

- undercut
- rolled edge
- correct location
- slag inclusion

SCALE

TEE JOINT

(OVERHEAD)

MP/23/3.6.2/10

MAT. MILDSTEEL


ARC WELDING



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER




Ex.No.	Thickness t		Space mm	Electrode ϕ		Name of Electrode	Amps recommended	Amps. used
	mm	SWG inch		mm	SWG			
11	9.52							

SEQUENCE OF OPERATIONS


- Bevel and tack the pieces with root gap.
- Tack the job in overhead position.
- Deposit the root pass and obtain complete penetration.
- Remove the slag.
- Deposit additional passes to fill the groove.

Note Keep the arc as short as possible.

POSITION OF ELECTRODE



WORK ANGLE



TRAVEL ANGLE


SCALE	SINGLE V BUTT JOINT (over head)	MP/2.3/3.6.2/11
MAT. MILD STEEL		ARC WELDING



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER




Ex. No.	Thickness t		Space mm	Electrode ϕ		Name of Electrode	Amps recommended	Amps. used.
	mm	SWG		mm	SWG			
12	4.76			3.25				


POSITION OF ELECTRODE

WORK ANGLE 45°

TRAVEL ANGLE $70^\circ - 80^\circ$



WORK ANGLE



TRAVEL ANGLE


SCALE	PIPE ON PLATE (horizontal)	MP/2.3/3.6.2/12
MAT. MILD STEEL		ARC WELDING

DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING


PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER





Ex. No.	Thickness t		Space mm	Electrode ϕ		Name of Electrode	Amps. recommended	Amps used
	mm	SWG		inch	mm			
13					10			



1 = Base plate

2 = Deposit

3 = Copper or aluminium plate

1. When built-up-welding use a copper or aluminium plate on the edges of the deposit to get a sharp corner.

2. Weld the layers criss-cross!


SCALE:	BUILD-UP WELD FLAT	MP/2.3/3 6.2/13
MAT MILDSTEEL		ARC WELDING



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



Ex. No.	Thickness t			Space mm	Electrode ϕ		Name of Electrode	Amps recommended	Amps. used
	mm	SWG	inch		mm	SWG			
14	4.76								


SEQUENCE OF OPERATIONS

- Set the workpieces and tack the parts.
- Clamp the job in proper position.
- Deposit the bead with short arc without weaving.

POSITION OF ELECTRODE

Travel Angle $60^{\circ} - 70^{\circ}$

Work Angle 45°




SCALE	PIPE ON PLATE (T-joint fixed downward)	MP/2.3/3.6.2/14
MAT. MILD STEEL		ARC WELDING




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



Ex. No.	Thickness t		Space mm	Electrode ϕ		Name of Electrode	Amps. recommended	Amps used
	mm	SWG		inch	mm			
1)					10			



Position of the electrode when pipe welding in fixed position.


SCALE:	SINGLE V BUTT JOINT ON TUBE FL/V/O	MP/2.5/3.5 2/15
MAT: MILDSTEEL		ARC - WELDING




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER




Ex No.	Thickness t		Space mm	Electrode Ø		Name of Electrode	Amps recommended	Amps used
	mm	SWG		mm	SWG			
16					10			



SEQUENCE OF OPERATION

1. Clean, set up and tack weld the pieces.
2. Clamp the job in the position required.
3. Deposite the root run, clean it thoroughly and examine.
4. Weld the 2nd layer and clean it.
5. Weld the 3rd layer and clean the seam thoroughly.



Move around the joint while welding.
Do not turn the pipe.


SCALE:	SINGLE V BUTT JOINT	HORIZONTAL FIXED	MP/23/36 2/15
MAT MILDSTEEL			ARC WELDING



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER




Ex.No.	Thickness t			Space mm	Electrode ϕ		Name of Electrode	Amps recommended	Amps used
	mm	SWG	inch		mm	SWG			
17	6.35				4				

SEQUENCE OF OPERATIONS

- Counteract any tendency of deposited metal to fall towards the horizontal plate by increasing slightly the electrode angle to the vertical plate.
- Adjust the rate of travel so that a fillet weld of equal leg length of 5 mm is deposited.

Note Be sure the right kind of electrode for the type of stainless to be welded.

POSITION OF ELECTRODE




SCALE	T JOINT (horizontal)	MP/2.3/3.6.2/17
MAT. STAINLESS STEEL		ARC WELDING



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER




Ex. No.	Thickness t			Space mm	Electrode ϕ		Name of Electrode	Amps recommended	Amps used
	mm	SWG	inch		mm	SWG			
18	9.52								

SEQUENCE OF OPERATIONS

- Deposit the root run, using a very small crescent weaving motion.
- Deposit the second run, using a more Whip-stitch weave and bringing the weld to within 3 mm of the outer edges of the fusion faces.
- Deposit the third run, using a Hem-stitch weave in which the electrode is moved slightly upwards as the arc plays on the outer edge of each fusion face. Make sure that the deposit fills the V.

1st run weave Crescent Motion.
 2nd run weave Whip-stitch,
 3rd run weave Hem-stitch.

POSITION OF ELECTRODE
















SCALE	SINGLE V BUTT JOINT (vertical upward)	MP/2.3/3.6.2/18
MAT. STAINLESS STEEL		ARC WELDING




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER

<u>GTAW</u>		
 Straight Bead	 Square Butt Joint	 Straight Bead
1	2	3
 Square Butt Joint	 T Joint	 Square Butt Joint
4	5	6
<u>GMAW</u>		
 Straight Bead	 Square Butt Joint	 T Joint
7	8	9
 Straight Bead	 Square Butt Joint	 T Joint
10	11	12
	 Square Butt Joint	
	13	

103

TRADE TRAINING II	LAYOUT	MP/2-3/3-6-3
		GTAW/GMAW
 DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING PAK-GERMAN TECHNICAL TRAINING PROGRAMME		WELDER

MATERIAL REQUIRED

TRADE TRAINING II
GTAW/GMAW
NO:2.3/3.6.3/1 to 13

(Length given in millimeters


	1	2	3	4	5	6	7	8	9	10	11	12	13	Length per trainee	Length for 16 trainees
M.S.Flat 100x1.6 4"x1/16"	150													150	2.5m
M.S.Flat 50x1.6 2"x1/16"	900													900	14.5m
S.S.Sheet 100x1.2 4"x1/16"			150											150	2.5m
S.S.Sheet 50x1.2 2"x1/16"				900										900	14.5m
Al-Sheet 50x3				900	900								900	3600	58m
M.S.Flat 100x3							150							150	2.5m
M.S.Flat 50x3								900	900					1800	29 m
S.S.Sheet 100x3										150				150	2.5m
S.S.Sheet 50x3											900			900	14.5m
Al-Sheet 50x3													450	450	7.25m



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER




Ex.No	Thickness mm	swg	Filler Rod	Tungsten Electrode	Nozzel Size	Shielding Gas	Electrode Stick out	Current
1	1.6		1.6	2.4 Thoriated	9.5mm	Argon 4L/min.	5 mm	40-50 A DC

SEQUENCE OF OPERATIONS

- Clean the job with acetone.
- Establish the pool of molten metal, add filler rod.
- Hold a close arc, maintain a puddle of approximately 1/8" wide while forming a consistent bead across the plate.


CAUTION

- Use direct current straight polarity.
- Use tungsten electrode pointed tip.
- Do not touch the base metal and filler rod with tungsten electrode.



WORK ANGLE

POSITION OF TORCH AND FILLER ROD



TRAVEL ANGLE

SCALE	STRAIGHT BEAD (FLAT)	MP/2.3/3.6.3/1
MAT. MILD STEEL		GTAW




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER

105



Ex.No	Thickness		Filler Rod	Tungsten Electrode	Nozzel Size	Shielding Gas	Electrode Stick out	Current
	mm	swg						
6	3		2.5	3.2 mm Zirconia-ted.	12.7 mm	Argon 9-10L P/min.	5 mm	75-85A AC

SEQUENCE OF OPERATIONS

- Set up and tack the pieces at distance 70mm.
- Support in flat position with grooved fire brick.
- Establish the arc at the right hand end of the joint.
- Immediately on fusion of the root, add filler metal to prevent excessive fusion of parent metal.
- Move to the left without weaving of torch.
- Coordinate addition of filler metal and rate of travel so as to maintain fusion to the root and build up the weld to a slightly convex profile.


SCALE	SQUARE BUTT JOINT (FLAT)	MP/2.3/3.6.3/6
MAT. ALUMINIUM		GTAW



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME


WELDER




Ex.No	Thickness		Space	Electrode Wire	Nozzel Type	Shielding Gas	Arc volts	Current
	mm	swq						
7	3			0.8 mm	short reach	CO ₂ 14L/min.	19-20	110-130 A

SEQUENCE OF OPERATIONS

- Check the return lead is firmly connected to work piece and power source.
- Check all connections to wire feed and control unit are in good order.
- Check the gas hoses.
- Draw the straight line in the job.
- Set the gas flow and wire feed.
- Establish the arc at the right end.
- Adjust the travel speed to ensure the bead width and height is uniform.



POSITION OF GUN




SCALE	STRAIGHT BEAD (FLAT)	MP/2.3/3.6.3/7
MAT. MILD STEEL		GMAW



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER




Ex.No	Thickness		Filler Rod	Tungsten Electrode	Nozzel Size	Shielding Gas	Electrode Stick out	Current
	mm	swg						
4	1.2		1.6 mm	1.6 Thoriated	9.5 mm	Argon 4L/min.	5 mm	35-45 A DC


SEQUENCE OF OPERATIONS

- Set up and tack the pieces at distance 70 mm without gap.
- Establish the arc on the first tack and move quickly to the right hand end of joint to start welding.
- As soon as a small pool of molten metal is formed, add filler metal.
- Maintain the small depression in the base by moving the torch forward and feeding the filler rod into the main pool. Continue this action along the way to allow the weld to be reinforced sufficiently.

CAUTION

- Use argon backing bar.

SCALE	SQUARE BUTT JOINT (FLAT)	MP/2.3/3.6.3/4
MAT S STEEL		GTAW
 DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING PAK-GERMAN TECHNICAL TRAINING PROGRAMME		WELDER



Ex.No	Thickness mm.	swq	Filler Rod	Tungsten Electrode	Nozzel Size	Shielding Gas	Electrode Stick out	Current
5	3		3.2	3.2 Zirconiated.	12.7mm	Argon 6L/min.	5 mm	75-85 A AC


SEQUENCE OF OPERATIONS

- Set up and tack the pieces at both ends.
- Establish the pool on the right end.
- Add filler metal as soon as a pool of molten metal is formed.
- Adjust rate of travel.


CAUTION

- Use rounded tip tungsten electrode.

POSITION OF TORCH AND FILLER ROD



WORK ANGLE



TRAVEL ANGLE


SCALE	T JOINT (HORIZONTAL)	MP/2.3/3.6.3/5
MAT. ALUMINIUM		GTAW



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER




Ex.No	Thickness mm	Filler Rod	Tungsten Electrode	Nozzel Size	Shielding Gas	Electrode Stick out	Current
2	1.6	1.6 mm	2.4 Thoriated	9.5 mm	Argon 4L/min.	5 mm	40-50 A DC

SEQUENCE OF OPERATIONS

- Set up and tack the pieces.
- Deposit a bead using the joint in the center of the weld across the piece.
- Obtain complete penetration.


CAUTION

- Use direct current straight polarity.



WORK ANGLE

POSITION OF TORCH AND FILLER ROD



TRAVEL ANGLE


SCALE	SQUARE BUTT JOINT (FLAT)	MP/2.3/3.6.3/2
MAT MILD STEEL		GTAW



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER




Ex.No	Thickness mm	swg	Filler Rod	Tungsten Electrode	Nozzel Size	Shielding Gas	Electrode Stick out	Current
3	1.2		1.6 mm	1.6 mm Thoriated	9.5 mm	Argon 4L/min.	5 mm	35-45 A DC

SEQUENCE OF OPERATIONS

- Clean the job.
- Establish small pool of the molten metal, add filler rod.
- Adjust rate of travel to avoid excessive melting.


CAUTION

- Use DC current.



WORK ANGLE

POSITION OF TORCH AND FILLER ROD



TRAVEL ANGLE


SCALE	STRAIGHT BEAD (FLAT)	MP/2.3/3.6.3/3
MAT. S. STEEL		GTAW



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER




Ex.No	Thickness		Space	Electrode Wire	Nozzel Type	Shielding Gas	Arc volts	Current
	mm	swg						
8	3		1.5 to 2.5	0.8 mm	short reach	CO ₂ 14L/min.	18-19	85-95 A


SEQUENCE OF OPERATIONS

- Clean and tack the pieces.
- Establish the arc at the right hand end of the joint.
- Adjust the travel speed to ensure fusion of the spaced edges of the parent metal.
- Use small weaving motion side to side.
- Obtain complete penetration.

POSITION OF GUN



WORK ANGLE



TRAVEL ANGLE


SCALE	SQUARE BUTT JOINT (FLAT)	MP/2.3/3.6,3/8
MAT. MILD STEEL		GMAW



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER




Ex.No	Thickness		Space	Electrode Wire	Nozzel Type	Shielding Gas	Arc volts	Current
	mm	swq						
9	3		-	0.8 mm	short reach	CO ₂ 14L/min.	19-20	110-130 A

SEQUENCE OF OPERATIONS

- Set up and tack the pieces.
- Point the electrode wire at the root of the joint.
- Establish the arc at the right-hand end of the joint.
- Deposit the second pass overlapping half width of the first pass on both sides of the joint.
- Deposit the third pass overlapping the first and second passes on both sides of the joint.

POSITION OF GUN




SCALE	T JOINT (HORIZONTAL)	MP/2.3/3.6.3/9
MAT. MILD STEEL		GMAW



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER



Ex.No	Thickness mm	swg	Space	Electrode Wire	Nozzel Type	Shielding Gas	Arc volts	Current
10	3		-	0.8 mm	short reach	Ar + O ₂ 99% + 1% 14L/min.	19-20	110-130 A



SEQUENCE OF OPERATIONS

- After cleaning, mark the straight lines on the job.
- Set wire feed and gas flow.
- Adjust the rate of travel.

CAUTION

- Use direct current reserve polarity.

POSITION OF GUN



SCALE

STRAIGHT BEAD (FLAT)

MP/2.3/3.6.3/10


MAT. STAINLESS. S.

GMAW

DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER




Ex.No	Thickness		Space	Electrode Wire	Nozzel Type	Shielding Gas	Arc volts	Current
	mm	swq						
11	3		1.5 to 2.5	0.8 mm	short reach	Ar + O ₂ 99% + 1% 14L/min.	19-20	110-130 A

SEQUENCE OF OPERATIONS


- Set up and tack the pieces with gap.
- Set the job on copper back up strips.
- Establish the arc at the right hand of the joint.
- Adjust the travel speed to secure fusion of the spaced edges of the parent metal.
- Obtain complete penetration.

CAUTION

- Use copper back up strips.



COPPER BACK UP STRIPS




SCALE	SQUARE BUTT JOINT (FLAT)	MP/2.3/3.6.3/11
MAT. STAINLESS. S.		GMAW



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER




Ex.No	Thickness mm	swg	Space	Electrode Wire	Nozzel Type	Shielding Gas	Arc volts	Current
12	3		-	1.2 mm	long reach	Argon 17L/min.	24	180 A


SEQUENCE OF OPERATIONS

- Set up and tack the pieces.
- Establish the arc at the right hand end of the joint.
- Deposit the bead with equal leg length.

POSITION OF GUN



WORK ANGLE



TRAVEL ANGLE


SCALE	T JOINT (HORIZ ANTAL)	MP/2.3/3.6.3/12
MAT. ALUMINIUM		GMAW



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER




Ex.No	Thickness mm	swg	Space	Electrode Wire	Nozzel Type	Shielding Gas	Arc volts	Current
13	3		-	1.2 mm	long reach	Argon 17L/min	24	160 A


SEQUENCE OF OPERATIONS

- Set up and tack the pieces with gap.
- Establish the arc on the tack weld at the right hand of the joint.
- As soon as pool of molten metal is formed to full depth of joint prepared, move the gun progressively leftwards.
- Adjust the rate of travel so that the deposit fills the joint.
- Complete the weld by fusing into the tack weld at the left hand end of the joint.

POSITION OF GUN



WORK ANGLE



TRAVEL ANGLE

SCALE	SQUARE BUTT JOINT (FLAT) (with backing strip)	MP/2.3/3.6.3/13
MAT. ALUMINIUM		GMAW



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

WELDER

